



Vehicle History Summary



Fleet #	CT15
Registration	YQ74NH
Make	Graham Lusty
Model	Side Tipper
VIN / Chassis #	6V9GLT3TRDB012556
Build Date	2013

Date	Reading / Units	Type / Repairer Notes	Repairer
Breakdown, Hydraulics - IMPORTANT R-11510			Daniel Farinha - Misso's
27/11/2025	614,039 kms	A - 12 Wks S-8019 Carried out A Service as per Service sheet Cross member top and bottom cracked right around - Needs repairing	Mitch Grima
19/11/2025	609,289 kms	Fault, Inspection T-968 Tyres legal at time of inspection	Mitch Grima
18/10/2025	586,123 kms	Hydraulics - IMPORTANT, Planned Maintenance R-10449 Removed and replaced Cylinder with Resealed component Tested, all operational No leaks	Daniel Farinha - Misso's, Mitch Grima
18/10/2025	586,123 kms	A - 12 Wks S-7633 Carried out A Service as per Service sheet Replaced Front Lift cylinder with refurbished cylinder	Daniel Farinha - Misso's
30/09/2025		Fire Extinguisher Inspection I-2653	Pyro Dynamics Pty Ltd
30/09/2025	578,879 kms	Breakdown, Tarp - IMPORTANT R-10549 Repaired broken cable bracket and replaced cable Re-adjusted pole alignment and repaired pole support strap on bailing arm	Matthew Twitchett
11/09/2025		Planned Maintenance, Tarp - IMPORTANT R-10346 Replaced corroded fuse holder Tested, all operational	Matthew Twitchett
25/08/2025	556,473 kms	A - 12 Wks S-6979 Carried out A Service as per Service sheet In Addition Jacked all axles and inspected Wheel bearing adjustments Adjusted Pos 1 Wheel bearing	Aaron McCully, Daniel Farinha - Misso's, Mitch Grima
22/08/2025		Breakdown, Suspension - URGENT R-10121 Removed and replaced Pos 6 Airbag	Mitch Grima
06/08/2025	543,663 kms	A - 12 Wks S-6740 Carried out A Service as per Service sheet	Mitch Grima
06/08/2025	543,663 kms	Opportune Maintenance, Suspension - URGENT R-10574 Removed and replaced Pos 5 & 6 Shock absorbers with new hardware kit	Mitch Grima
06/08/2025	543,663 kms	New T-1016 Removed and replaced Pos 6 Tyres Carried out re-torque	Mitch Grima
21/07/2025		Non-Destructive Testing Inspections - 12 Monthly I-2519 King Pin Mount - No cracking detected Turntable - No cracking detected	DTIS QLD PTY LTD
08/07/2025	526,929 kms	A - 12 Wks S-6382 Carry out A service as per service sheet	Daniel Farinha - Misso's, Mitch Grima

Date	Reading / Units	Type / Repairer Notes	Repairer
21/06/2025	519,142 kms	Breakdown, Tarp - IMPORTANT R-9458 Repaired damaged corroded wiring. Replaced corroded plugs and tested motor. Replaced battery and tested all OK.	Matthew Twitchett
03/06/2025	513,112 kms	A - 12 Wks S-6082 Carried out A Service as per Service sheet attached	Matthew Twitchett
21/05/2025	504,846 kms	Compliance T-831 All tyres are in road worthy condition, Some not at wear indicators yet, Pressures good Indicators fitted	Matthew Twitchett
20/05/2025	504,487 kms	Compliance, King Pin - IMPORTANT, Skid Plate , Turntable - IMPORTANT R-9251 Inspected skid plate - Straight, no cracks, no wear Pin in correct position - in good condition Inspect turntable mounts - in good condition Inspect Turntable Jaws and horseshoe - in good condition	Matthew Twitchett, Peter Harris
20/05/2025		Brake Test 6 Months I-2155 Completed and passed 6 month Capcoal brake test	Hoppers Diesel and plant Hire
17/05/2025	501,442 kms	Tarp - IMPORTANT R-9208 Moved tarp forward and tested	Daniel Farinha - Misso's
13/05/2025	497,758 kms	Lights - IMPORTANT R-8931 Fixed wiring for brake park lights. Replaced 1 side clearance light.	Matthew Twitchett
12/05/2025	497,758 kms	A - 12 Wks S-5955 Carry out service as per service sheet R and R RHR clearance light Repaired RHR brake and park light	Matthew Twitchett, Peter Harris
23/04/2025	487,942 kms	Tarp - IMPORTANT R-8969 Replaced with s/h tarp and pole assembly	Joseph Parker, Matthew Twitchett, Troy Francken
05/04/2025	473,882 kms	Brake Test 6 Months I-2035 Complete brake test for VD82 CT22 D19 CT15 CT16	Nick Fenton
01/04/2025	473,853 kms	A - 12 Wks S-5820 Carried out A Service as per Service paperwork attached	Harry Louis, Jye Storch
26/03/2025	473,846 kms	Brakes - URGENT, Leak - IMPORTANT R-8636 Inspected Fault, Found hole in booster hose, cut out affected piece, reconnected hose with new clamps, tested operation, all ok	Harry Louis
26/03/2025	473,846 kms	Fault T-698 Remove and replace front axle with new tyres.	Harry Louis, Joseph Parker
09/03/2025	463,059 kms	A - 12 Wks S-5738 Carried out A Service as per Service sheet	Daniel Farinha - Misso's
24/01/2025		A - 12 Wks S-5555	Daniel Farinha - Misso's
14/12/2024		Brake Test 6 Months I-1783 Complete CONEQU and 6 monthly brake test - VD82 CT22 D19 CT15 CT16	Nick Fenton
19/11/2024		Turntable - IMPORTANT R-5461 Replaced turntable with a jost	Duane Hitch - Sourth East Mechanical
19/11/2024		Hydraulics - IMPORTANT R-6762 Replaced lift ram	Duane Hitch - Sourth East Mechanical
19/11/2024		Hydraulics - IMPORTANT R-7058 Replaced lift ram	Duane Hitch - Sourth East Mechanical
07/11/2024	431,583 kms	Body R-7392 Inspected & Repaired minor crack in bin on fish plate bracing	Troy Francken

Date	Reading / Units	Type / Repairer Notes	Repairer
04/11/2024	429,685 kms	Chassis R-7363 Inspected & repaired cracked cross member.	Troy Francken
31/10/2024	429,685 kms	Lights - IMPORTANT R-7208 Could not fault at time of inspection.	Matthew Twitchett
28/10/2024	429,582 kms	C - 12 Mnths S-5202 Replaced brake shoes, braile drums and bearings.	Duane Hitch - Sourth East Mechanical
28/10/2024	429,582 kms	Compliance, King Pin - IMPORTANT, Skid Plate , Turntable - IMPORTANT R-7273 Carry out hitching inspection. Replace king pin. Inspect turntable feet and jaw.	Duane Hitch - Sourth East Mechanical
28/10/2024		Turntable - Ringfeeder and Kingpin Inspection I-1684	Duane Hitch - Sourth East Mechanical
25/10/2024	429,281 kms	A - 12 Wks S-5191 Turntable u/s - Replaced turntable R5461 Front crossmember cracked - Refer to R	Duane Hitch - Sourth East Mechanical, Harry Louis, Matthew Twitchett
19/10/2024		Brake Test Annual I-1631 Complete Vulcan compliance - VD82 CT22 D19 CT15 CT16	Damian Ryan
26/09/2024	413,864 kms	A - 12 Wks S-4958 See attached jobcard	Duane Hitch - Sourth East Mechanical
25/08/2024		A - 12 Wks S-4778 See attached jobcard	Duane Hitch - Sourth East Mechanical
31/07/2024	381,189 kms	Lights - IMPORTANT R-6442 See attached jobcard Replaced.	Joseph Parker, Peter Harris
31/07/2024	381,189 kms	Retighten Wheels, Run Out T-261 See attached jobcard Travel, retorque wheels, travel back.	Genecy Dos Santos
31/07/2024	381,189 kms	A - 12 Wks S-4539 See attached jobcard	Joseph Parker, Peter Harris
31/07/2024	381,189 kms	Lights - IMPORTANT R-6327 See attached jobcard Repaired.	Joseph Parker, Peter Harris
10/07/2024	371,739 kms	Tippling R-6252 See attached jobcard	Matthew Twitchett
24/06/2024		A - 12 Wks S-4377 See attached jobcard	Matthew Twitchett
17/06/2024	360,050 kms	Run Out T-202 See attached jobcard Travel for wheel changes.	Genecy Dos Santos
15/06/2024		Conneq Pre Inspection I-1263 Complete CapCoal CONEQU pre inspection and brake test - PASS	Damian Ryan
15/06/2024		Brake Test 6 Months I-1330 Complete MBN 24W Brake Test - PASS VD82_CT22_D19_CT15_CT16	Gregory Fing
09/06/2024	354,052 kms	Tarp - IMPORTANT R-6006 See attached jobcard Added another 150mm cable to extend cable, tested and rolled back fine.	Jonathan Rafferty - Misso
30/05/2024	346,427 kms	A - 12 Wks S-4251 See attached jobcard	Duane Hitch - Sourth East Mechanical

Date	Reading / Units	Type / Repairer Notes	Repairer
15/05/2024	330,049 kms	A - 12 Wks S-4108 See attached jobcard Reflecting tape added to door. Replaced POS 3 airbag.	Peter Harris
17/04/2024	322,289 kms	A - 12 Wks S-3999 See attached jobcard	Duane Hitch - Sourth East Mechanical
02/04/2024	313,130 kms 6,523 hrs	Brakes - URGENT R-5022 See attached jobcard	Matthew Twitchett, Sione Lousi
02/04/2024	313,130 kms 6,523 hrs	Suspension - URGENT R-5025 See attached jobcard Replaced POS 1 air bag due to large leak.	Sione Lousi
28/03/2024	308,884 kms	Suspension - URGENT R-4908	Adam Wilson
27/03/2024		Turntable - Ringfeeder and Kingpin Inspection I-1048 See attached report	Joseph Parker
26/03/2024	308,884 kms	A - 12 Wks S-3734 See attached jobcard	Adam Wilson
23/02/2024		Electrical - IMPORTANT, Tarp - IMPORTANT R-4508 See attached jobcard Inspected wiring, insulated wiring and secured	Jonathan Rafferty - Misso
15/02/2024		Fire Extinguisher R-4010	Ryan Rosman - TMT Mechanical
15/02/2024		Wheels/Tyres - URGENT R-3568	Ryan Rosman - TMT Mechanical
14/02/2024	284,085 kms 5,882 hrs	A - 12 Wks S-3618 See attached jobcard	Daniel Farinha - Misso's
08/02/2024		Tarp - IMPORTANT R-4329 See attached jobcard Inspected and Replaced Tarp Battery	Duane Hitch - Sourth East Mechanical
26/01/2024		Turntable - Ringfeeder and Kingpin Inspection I-867 See attached inspection report	Duane Hitch - Sourth East Mechanical
26/01/2024		A - 12 Wks S-3489 See attached jobcard Fire Extinguisher bracket broken - replace bracket JP	Duane Hitch - Sourth East Mechanical
03/01/2024		A - 12 Wks S-3361 See attached jobcard Broken grease lines - replaced grease lines	Tim Brogden - JSF
11/12/2023		Damage R-3595 See attached jobcard 3595 Crack repairs to door hinge	Internal Workshop
05/12/2023		A - 12 Wks S-3250 See attached jobcard Pos 3 & Pos 4 Tri Functional bushes worn - W/o Replace bushes at B Service Pos 5 Shocky bushes worn - removed and replaced All tyers were replaced, hub meter installed - Good / serviceable tyres were kept and others disposed of R & R all tyres, torqued and tagged in truck Pos 3 & Pos 5 Wheel bearing require adjusting - Carried out wheel bearing adjustment and regrease	Daniel Breen - TMT
01/12/2023		King Pin - IMPORTANT, Turntable - IMPORTANT R-3465 See attached jobcard 3465 Replaced king pin	Internal Workshop
17/11/2023		A - 12 Wks S-3126 See attached service jobcard 3126 Pos 2 slack adjuster siezed - removed slack adjuster didnt have new one in stock, managed to free the adjuster, re-fitted and adjusted brakes Pos 6 brake booster hose clamp leaking - removed clamp cut back hose fitted new hose clamp Brake hoses rubbing - secured brake hoses with cable ties Brake hoses are becoming hard and brittle something to keep eye on	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
23/10/2023	221,812 kms	Suspension - URGENT R-2853 See attached jobcard Greased Moved until adjuster worked Test ok	Andrew Mollard
23/10/2023		A - 12 Wks S-3028 See attached jobcard Pos 2 air bag leak - replaced air bag Pos 4 air bag leak - replaced air bag	Andrew Mollard
05/10/2023		A - 12 Wks S-2920 A Service carried out as per service record - CS	Internal Workshop
05/10/2023		Leak - IMPORTANT R-2732 No fault found	Internal Workshop
05/10/2023		C - 12 Mnths S-2388 C Service carried out as per service record - CS Replaced RH reflector	Internal Workshop
21/09/2023		A - 12 Wks S-2824 See attached service job card 2824 Left clearance light not working light faulty - Remove, fit and wire clearance light and check ok Bin back wall bent inwards	Internal Workshop
14/09/2023		Lights - IMPORTANT R-2609 See attached repair job card 2609 R&R Clearance light left front Attend to complaint of number plate light not working, carry out test, locate cause to faulty number plate light, remove, replace and test ok.	Internal Workshop
10/09/2023		Leak - IMPORTANT R-2248 Could not fault at time of inspection	Internal Workshop
10/09/2023		Turntable - IMPORTANT R-2425 Replaced turntable with second hand one - 90MM pin unit	Internal Workshop
10/09/2023		Leak - IMPORTANT R-2312 Can not fault - Has been repaired	Internal Workshop
20/08/2023		A - 12 Wks S-2727 A service carried out as per service record - DJ/TC Adjusted all three wheel bearings on POS1 POS3, POS4 Fitted new tyre POS3 Remove and replace booster leak POS6	Internal Workshop
16/08/2023		Wheels/Tyres - URGENT R-1903 Replaced	Internal Workshop
16/08/2023		Leak - IMPORTANT R-2311 Found diff lock was on	Internal Workshop
25/07/2023		A - 12 Wks S-2518 A Service carried out as per service report R-1903 - Repaired - Replaced tyres	Lincoln Wild - LW Diesel & Contracting Services Pty Ltd
25/07/2023		A - 12 Wks S-2599 A Service carried out as per service report	Ryan Rosman - TMT Mechanical
26/06/2023		Wheels/Tyres - URGENT R-1838 Remove and Replace tyres LHM inner and outer	Hugh Middleton VDPH Maintenance Coordinator
26/06/2023		Lights - IMPORTANT R-1797 Remove and Replace correct red amber lamp	Hugh Middleton VDPH Maintenance Coordinator
21/06/2023		Leak - IMPORTANT R-1842 Inspected air leak from R12 valve. Removed and Replaced valve. Replaced hose clamps on brake hoses. Replaced 3/8 T-Piece and 90° fitting in valves. Replaced signal lines. Run up and tested all ok	Ryan Rosman - TMT Mechanical
15/06/2023		King Pin - IMPORTANT R-1764	Nick Fenton

Date	Reading / Units	Type / Repairer Notes	Repairer
09/06/2023		A - 12 Wks S-2350 A Service carried out as per service report 1st Axle RHS tyres flat spots - R.K Repaired RHS 2nd Axle shocker damaged - R.K Repaired LHS 3rd Axle Shocker Damaged - R.K Repaired Hydraulic fittings leaking - Replaced	Duane Hitch - Sourth East Mechanical, Randall Kruger - ADS
05/06/2023		Other R-1718 Remove and Replaced mudflap	Internal Workshop
18/05/2023		A - 12 Wks S-2245 A Service carried out as per service report RHS Rear side marker broken - Repaired fitted new led light Cracks on body of trailer - (Boily's) HM Crack front LHS of chassis - Boily's HM	Duane Hitch - Sourth East Mechanical
16/05/2023		King Pin - IMPORTANT R-1530	Nick Fenton
11/05/2023		King Pin - IMPORTANT R-1535 Change 90mm king pin to 50mm King pin	Duane Hitch - Sourth East Mechanical
29/04/2023		A - 12 Wks S-2139 A Service carried out as per service report Rear and side light out - Fixed wiring	ATL Diesel Services - Jordan Hasenkam
29/04/2023		Tarp - IMPORTANT R-1454 Change out broken tarp pole wire	Duane Hitch - Sourth East Mechanical
22/04/2023		Tarp - IMPORTANT R-1350 Refitted tarp pole end that fell out and fixed wiring fault on tarp battery causing fuse to blow.	Randall Kruger - ADS
19/04/2023		Wheels/Tyres - URGENT R-1361 Changed x4 tyres	ATL Diesel Services - Jordan Hasenkam
12/04/2023		A - 12 Wks S-2026 A Service carried out as per service report Pos 6 tyres u/s - Ticked RB LH rear marker not working - Ticked RB Door fittings loose on front with oil leak - Ticked RB	Internal Workshop
06/04/2023		Wheels/Tyres - URGENT R-1152 Removed and Replaced old shocker on Axle 1 RHS / Axle 2 LHS / Axle 3 RHS	Internal Workshop
26/03/2023		A - 12 Wks S-1928 A Service carried out as per service report 1st Axle L/H Tyres need replacing - Replaced x3 shocks need replacing. 1st axle R/H, 2nd axle L/H, 3rd Axle R/H (Bushes cracked) Trailers loaded, needs to be unloaded and over the pit for repair. Missing bin box internal cable - Boily repaired.	Randall Kruger - ADS
26/03/2023		Damage R-1141 Repaired with Service S1928 on the 26.03.23	Randall Kruger - ADS
10/03/2023		A - 12 Wks S-1843 A Service carried out as per service report Side lights down RHS not working	Randall Kruger - ADS
21/02/2023		A - 12 Wks S-1751 As per service sheet	ATL Diesel Services - Jordan Hasenkam
08/02/2023		A - 12 Wks S-1675 As per Service Report	Randall Kruger - ADS
25/01/2023		A - 12 Wks S-1637 As per Service Report	Luatasi Anesone Atileo
11/01/2023		Fire Extinguisher Inspection I-461	Internal Workshop
11/01/2023		C - 12 Mnths S-1400	Hugh Middleton VDPH Maintenance Coordinator
15/12/2022		King Pin - IMPORTANT R-633	Nick Fenton

Date	Reading / Units	Type / Repairer Notes	Repairer
14/12/2022		Fire Extinguisher Inspection I-459	Internal Workshop
14/12/2022		A - 12 Wks S-1397 3rd axle L/H inner tyre needs replacing Loose arm for suspension ride height valve	Randall Kruger - ADS
01/12/2022		A - 12 Wks S-1353 Serviced by Michael Beran	Rob Brackowski - Callcorr
03/11/2022		C - 12 Mnths S-1208 C Service repack all hubs R&R King pin R&R LH & RHF shockers	Hugh Middleton VDPH Maintenance Coordinator
12/09/2022		A - 12 Wks S-1097	ATL Diesel Services - Jordan Hasenkam
30/08/2022		Wheels/Tyres - URGENT R-472 tyers replaced	Hugh Middleton VDPH Maintenance Coordinator
30/08/2022		Lights - IMPORTANT R-473 new lamp fitted	Hugh Middleton VDPH Maintenance Coordinator
30/08/2022		Other R-471 replaced at service	Hugh Middleton VDPH Maintenance Coordinator
30/08/2022		A - 12 Wks S-1039 LHM shocker replaced	Hugh Middleton VDPH Maintenance Coordinator
23/08/2022		A - 12 Wks S-1017 RH INNER REAR INDICATOR LAMP IN OP - NEW	Hugh Middleton VDPH Maintenance Coordinator
05/08/2022		Fire Extinguisher Inspection I-263 LAST SERVICE MAY 2022 - AS PER INSPECTION REPORT S -959 05/08/2022	Internal Workshop
05/08/2022		A - 12 Wks S-959 SHOCKER MOUNT BUSH - REPLACED RHM BOOSTER - REPLACED RHM TYRE - REPLACED	Hugh Middleton VDPH Maintenance Coordinator
21/07/2022		Brake Test Annual I-357 PASS- For MNM	Gregory Fing
26/06/2022		A - 12 Wks S-854 Nil defects at inspection	ATL Diesel Services - Jordan Hasenkam
09/06/2022		A - 12 Wks S-809	Nick Fenton
02/06/2022		Wheels/Tyres - URGENT R-303	Nick Fenton
31/05/2022		Fire Extinguisher Inspection I-203	Internal Workshop
12/05/2022		A - 12 Wks S-741	Hugh Middleton VDPH Maintenance Coordinator
29/04/2022		Damage R-232	Hugh Middleton VDPH Maintenance Coordinator
29/04/2022		Wheels/Tyres - URGENT R-233	Hugh Middleton VDPH Maintenance Coordinator

Date	Reading / Units	Type / Repairer Notes	Repairer
21/04/2022		A - 12 Wks S-676 LHR tail light inop - wiring replaced wheel nut indicator missing RHF - replaced oil leak at diverter - secured hose	Hugh Middleton VDPH Maintenance Coordinator
18/04/2022		Wheels/Tyres - URGENT R-209	Hugh Middleton VDPH Maintenance Coordinator
23/03/2022		A - 12 Wks S-605 new tyres RHR 23.3.22 RH 3rd outer tyre on limit - replaced, torqued to 650mm	Hugh Middleton VDPH Maintenance Coordinator
07/02/2022		A - 12 Wks S-370 As per inspection report LHF inner tyre flat spotted - New pair LHR RHF hub end float x 5 - Adjusted LHM RHM Hub end Float X 5 - Adjusted	Internal Workshop
04/02/2022		Tarp - IMPORTANT R-87	Hugh Middleton VDPH Maintenance Coordinator
04/02/2022		Lights - IMPORTANT R-89 Repair broken wire	Hugh Middleton VDPH Maintenance Coordinator
31/12/2021		Fire Extinguisher Inspection I-124 As per Inspection Report S370	Internal Workshop
13/12/2021		Brake Test MNM 3 Monthly I-77 Brake Test - PASS	Nick Fenton
09/12/2021		King Pin - IMPORTANT R-6 Replace King Pin for Cap Coal Compliance	Nick Fenton
16/09/2021		B - 12 Mnths S-49 B TRAILER SERVICE - Completed	Internal Workshop

Signed: _____

Name: _____

Date: _____