



Vehicle History Summary



Fleet #	VD21
Registration	XB98HZ
Make	Kenworth
Model	K200
VIN / Chassis #	6F5000000KA466606
Build Date	2019

Date	Reading / Units	Type / Repairer Notes	Repairer
		Air Conditioner R-11864	
		Leak - IMPORTANT, Windscreen/Mirrors - IMPORTANT R-11833	
		Fault T-1046	
		Chassis R-12301	
		Damage R-12300	
		Lights - IMPORTANT R-12299	
		Damage R-12298	
		Lights - IMPORTANT R-12295	
		Damage R-12067	
		Steering - URGENT R-12066	
		WINDSCREEN WASHER / WIPER - IMPORTANT R-11834	
		Brakes - URGENT R-11831	
		Lights - IMPORTANT R-12302	
06/02/2026	263,227 kms 12,941 hrs	Radiator - IMPORTANT R-11977 Radiator mounting cross member cracked on LHS - x member Repaired mounts replaced thermostat to leader tank hose Gearbox cooler hoses both replaced LHS shockie mount inspected having multiple cracks in chassis, cracks gauged out and filled - mounting stud machined flat	Huntter Cannell
05/02/2026	263,227 kms 12,941 hrs	Airbag R-11994 Truck inspected for silent air leaks Found POS 3 front, POS 5 front, POS 6 rear air bag leaking	Huntter Cannell
03/02/2026	263,223 kms 12,941 hrs	Lights - IMPORTANT R-11976 RHS marker lamp U/S - ordered new light - on back order Centre clearance cab roof light tested operation - no fault found	Huntter Cannell
28/01/2026	260,541 kms 12,904 hrs	Engine mount repairs R-11932	Huntter Cannell

Date	Reading / Units	Type / Repairer Notes	Repairer
		Front engine mounts inspected unserviceable Rear engine mounts serviceable Front engine mounts replaced & crossmember removed & cleaned	
27/01/2026	260,541 kms 12,904 hrs	Damage R-11832	Huntter Cannell
		RH step support bracket to head light panel bent - panel bent straight and refitted RH mud guard bracket straightened & mud flap replaced RH upper step straightened	
27/01/2026	260,541 kms 12,994 hrs	Diff R-11748	Huntter Cannell
		Diff oil inspected Oil found overdue for change - burnt oil No major metal Oil refilled	
27/01/2026	260,541 kms 12,904 hrs	Engine mount repairs, Lights - IMPORTANT, step R-11952	Huntter Cannell
		- Front engine mounts - Rear drive line uni - RH step brackets - Panel beat - RH steer replaced - LHS rear tank clearance lights wiring repaired	
27/01/2026	260,541 kms 12,904 hrs	B - 30,000 S-8299	Huntter Cannell
		B Service completed - engine oil & differential front & rear oil and filters changed Repairs - Front engine mounts - Rear drive line uni - RH step brackets - Panel beat - RH steer replaced - LHS rear tank clearance lights wiring repaired	
16/01/2026	12,842 hrs	Leak - IMPORTANT, Windscreen/Mirrors - IMPORTANT R-11766	Mark Matchett
		Hosed down cab could not get too leak	
15/01/2026	12,842 hrs	Damage R-11681	Nicholas Deguara
		Inspected damage, no repair required at this point Damage to light bar and cab rear wiring, photos have been sent to Mark.	
15/01/2026	12,742 hrs	Missing R-11680	Nicholas Deguara
		Repaired wiring to anderson plug Fitted a new plug	
15/01/2026	12,842 hrs	Damage R-11755	Nicholas Deguara
		Inspected rear tail light bar, no repair required Inspected L/H rear cab wiring, no repair needed	
15/01/2026	12,842 hrs	Brakes - URGENT R-11754	Nicholas Deguara
		Truck has auto slack adjusters and look serviceable Brakes are not over stroking	
15/01/2026	12,842 hrs	Fire Extinguisher R-11749	Nicholas Deguara
		Serviced fire extinguisher and stamped dates	
15/01/2026	12,842 hrs	Windscreen/Mirrors - IMPORTANT R-11682	Nicholas Deguara
		fill windscreen wash bottle with fluid Unblock all lines with air	
14/01/2026	12,842 hrs	Electrical - IMPORTANT R-11753	Nicholas Deguara
		Replace trailer plug & repair wiring Inspected lights causing and appear to be serviceable check integrity next service.	
03/12/2025	245,287 kms 12,668 hrs	Chassis R-10737	
		REPAIR LEFT GAURD AND REPLACE BROKEN BRACKET AS REQUIRED	
02/12/2025	245,287 kms 12,668 hrs	A - 15,000 S-8046	Huntter Cannell
		A Service & inspection done POS 3 hub seal failed bearing had worn through - replaced all components throughout All fuel tank & diff breathers blown out and cleaned Grill re-afixed - bolts had rattled loose	
01/12/2025	245,287 kms 12,668 hrs	Hub Bearing / Seal - Urgent R-10740	Huntter Cannell
		Wheel seal failure Hub seal replaced & all component thoroughly cleaned Bearings inspected in Serviceable condition Diff oil changed	
10/09/2025	227,951 kms 12,343 hrs	A - 15,000 S-5881	Shane Alford - SGA

Date	Reading / Units	Type / Repairer Notes	Repairer
		Gearbox input seal weeping Clutch & brake adjusted Front spring hanger pins and bushes U/S	
05/08/2025	227,951 kms 12,343 hrs	Windscreen/Mirrors - IMPORTANT R-10741	Riley Steindl
		Fix windscreen washer wiring	
05/08/2025	227,951 kms 12,343 hrs	Cab R-10743	Riley Steindl
		Cab end of lift rams was flogged out Welded in machined washers and new pins to rectify issue	
05/08/2025	227,951 kms 12,343 hrs	Fuel Tank R-10745	Riley Steindl
		PTO flange resealed	
05/08/2025	227,951 kms 12,343 hrs	Lights - IMPORTANT R-10742	Riley Steindl
		Left front headlight replaced and issue rectified Multiple lights fixed on marker panels	
05/08/2025	227,951 kms 12,343 hrs	Cab R-10736	Riley Steindl
		Mount repaired and all new bolts installed	
05/08/2025	227,951 kms 12,343 hrs	Windscreen/Mirrors - IMPORTANT R-10744	Riley Steindl
		Window cracked was made aware and was proceeded to a monitor situation	
04/07/2025	220,087 kms 12,222 hrs	Cab R-8693	Internal Workshop
		TRIFFET REPLACED DOOR CARD CHRISTMAS TREE CLIPS AND REFITTED AL OK	
19/06/2025	216,574 kms 12,161 hrs	Lights - IMPORTANT R-8650	Shane Alford - SGA
		LIGHTS CHECKED ALL OK AT TIME OF INSPECTION	
19/06/2025	216,574 kms 12,161 hrs	WINDSCREEN WASHER / WIPER - IMPORTANT R-8585	Shane Alford - SGA
		U KINK HOSE AND ADJUST SPRAYS TEST OPERATION ALL OK	
19/06/2025	216,574 kms 12,161 hrs	Lights - IMPORTANT R-8642	Shane Alford - SGA
		NO FUAULT FOUND ALL LIGHTS WORKING	
19/06/2025	216,574 kms 12,161 hrs	Wheels/Tyres - URGENT R-8528	Shane Alford - SGA
		KING PINS REPLACED PREVIOUS DATE ALL FRONT END INSPECTED AND ALL OK FRONT TYRES REPLACED AT PREVIOUS TIME AND ALL OK TEST DRIVE AND NO ISSUES FOUND WITH FRONT END	
19/06/2025	216,574 kms 12,161 hrs	Electrical - IMPORTANT R-8518	
		SWAP OUT TWO WITH OTHER UNIT TEST AND NO ISSUES FOUND	
19/06/2025	216,574 kms 12,161 hrs	Leak - IMPORTANT R-9010	VDPH Sarina
		FRANK REPLACED AIR LINES AS REQUIRED	
19/06/2025	216,574 kms 12,161 hrs	RADIO R-8886	Campbell Ferrington
		TEST OPERATION OF RADIO ALL WORKS FINE TEST 2 DIFFERENT BLUETOOTH DEVICES AND ALL OK NO FAULT FOUND	
19/06/2025	216,574 kms 12,161 hrs	Cab R-8696	Shane Alford - SGA
		TEST HARNESS ALL OK TEST GAUGE ALL OK REPLACE SENSOR AND TEST ALL OK	

Date	Reading / Units	Type / Repairer Notes	Repairer
19/06/2025	216,574 kms 12,161 hrs	Steering - URGENT R-8695 FRONT TYRES HAVE BEEN REPLACED AND WHEEL ALIGNMENT COMPLETED TEST DRIVE AND NO ISSUES	Shane Alford - SGA
19/06/2025	216,574 kms 12,161 hrs	A - 15,000 S-5624 SERVICE COMPLETED ALL OK	Shane Alford - SGA
19/06/2025	216,574 kms 12,161 hrs	B - 30,000 S-6172 COMPLETE SERVICE AS PER SERVICE SHEET COMPLETE CHECK OVER AND REPAIR DEFECTS AS PER JOB CARDS	Shane Alford - SGA
28/04/2025	209,100 kms 12,040 hrs	Fuel Tank R-8670 FUEL TANK CAPS REPLACED	Internal Workshop
28/04/2025	209,100 kms 12,040 hrs	Fuel Tank R-8881 REPLACE FUEL TANK CAPS	
15/03/2025		Communication System - URGENT R-8355 REPACE AIRIEL AND TEST OPERATION ALL OK	Internal Workshop
12/03/2025		Air Conditioner R-8129 SERVICE ICEPAK REPLACE ICEPAK ALTERNATOR AND STARTER MOTOR CHECK OPERATION ALL OK CHECK OPERATION OF STANDBY FEATURE AND ALL WORKS CORRECTLY WHEN SWITCHES IN CORRECT SPOT	Internal Workshop
10/03/2025	200,765 kms 11,891 hrs	Electrical - IMPORTANT R-8138 REMOVE TRAILER HOSE PIVOT BAR AND REPAIR DAMAGED BRACKET REASSEMBLE AND TEST ALL OK	
10/03/2025	200,765 kms 11,891 hrs	Air Conditioner R-8309 REPLACE BLOWER FAN AND TEST OPERATION ALL OK	VDPH Sarina
09/03/2025		Electrical - IMPORTANT R-7983 REMOVE AND REPAIR TRUCK TO TRAILER HOSE HOLDER AS REQUIRED REASSEMBLE AND TEST ALL OK	Internal Workshop
06/03/2025	200,498 kms	Leak - IMPORTANT R-8277 REPLACE AIR GOVENOR HOSES RUN UP AND TEST ALL OK	
06/03/2025	200,948 kms	Damage R-7590 REPLACE 4 X REAR MUD GAURDS AND REPAIR REAR LIGHT BAR	Internal Workshop
06/03/2025	200,498 kms	Engine R-7986 CHECK OVER ALL OK ENGINE SOUNDS FINE AT TIME OF CHECK OVER	Internal Workshop
06/03/2025	200,498 kms	Communication System - URGENT R-8237 REPLACE AIRIEL WHIP TEST RADIOS ALL OK	Internal Workshop
04/03/2025	195,847 kms 11,796 hrs	WINDSCREEN WASHER / WIPER - IMPORTANT R-7936 ADJUST SPRAY NOZZLES AND TEST OPERATION ALL OK	Internal Workshop
26/02/2025	199,984 kms 11,866 hrs	Brakes - URGENT R-8244 road test truck and check operation of brakes all ok inspect and check operation of all brakes as required, adjust brakes all ok no adjustment required all valves operate in correct intended purpose	VDPH Sarina
20/02/2025	182,382 kms 11,585 hrs	King Pin - IMPORTANT R-7580 TURN TABLE REBUILT	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
07/02/2025	11,840 hrs	Air Dryer R-7924 REPLACE AIR LINES AS REQUIRED run and test all ok	Robert Brackowski
05/02/2025	197,793 kms 11,825 hrs	B - 30,000 S-5606 COMPLETE SERVICE AND CHECK OVER MUD GAURDS ON ORDER	VDPH Sarina
30/01/2025	197,793 kms 11,825 hrs	Electrical - IMPORTANT R-7389	Internal Workshop
30/01/2025	197,793 kms 11,825 hrs	Fire Extinguisher R-6547	Internal Workshop
30/01/2025	197,793 kms 11,825 hrs	Cab R-7239	Internal Workshop
30/01/2025	197,793 kms 11,825 hrs	Communication System - URGENT R-7206	Internal Workshop
30/01/2025	197,793 kms 11,825 hrs	Communication System - URGENT R-7729	VDPH Sarina
03/01/2025	180,228 kms 11,548 hrs	Missing R-7538 20/11/2024 - Label ordered Labeled received given to maintenance	Tina O'Hare
06/11/2024	175,965 kms	Driveline R-6952 Connect to correct gauge.	Jayden Sim
31/10/2024	175,965 kms 11,492 hrs	Engine R-6790 Engine has been tuned.	North Queensland Diesel
31/10/2024	175,963 kms 11,492 hrs	Turntable - IMPORTANT R-7262	Jayden Sim
31/10/2024	175,963 kms 11,492 hrs	B - 30,000 S-5193 Front LHS shock top mount worn hole in chassis. Welded up & redrilled.	Frank Hale - All Crane & Heavy Vehicle Repairs
30/10/2024	175,963 kms 11,492 hrs	Wheels/Tyres - URGENT R-7205 King pins have been replaced, RHS, LHS, grease.	Frank Hale - All Crane & Heavy Vehicle Repairs
29/10/2024	175,963 kms 11,492 hrs	Suspension - URGENT R-7264 Replaced transverse rod bush axle 2,3 RHS, LHS.	Frank Hale - All Crane & Heavy Vehicle Repairs
29/10/2024	117,596 kms 11,492 hrs	Engine R-6787 B Service been done, repairs.	Frank Hale - All Crane & Heavy Vehicle Repairs
29/10/2024	175,963 kms 11,492 hrs	Suspension - URGENT R-7266 Replaced shockies axle 2 RHS, LHS.	Frank Hale - All Crane & Heavy Vehicle Repairs
28/10/2024	175,963 kms 11,492 hrs	Lights - IMPORTANT R-6791 Steve has fitted work light back of cab.	Frank Hale - All Crane & Heavy Vehicle Repairs
28/10/2024	175,963 kms	Steering - URGENT R-7265	Jayden Sim

Date	Reading / Units	Type / Repairer Notes	Repairer
28/10/2024	175,963 kms 11,492 hrs	Fire Extinguisher R-7263 Fire extinguisher been replaced in tool box.	Frank Hale - All Crane & Heavy Vehicle Repairs
28/10/2024	175,963 kms	Lights - IMPORTANT R-6953	Jayden Sim
28/10/2024	175,963 kms 11,492 hrs	HORN R-6546 Reverse alarm been fix (been replaced). Horn has repaired.	East Coast Auto Electrical & Air Conditioning
16/09/2024	163,013 kms 11,295 hrs	Steering - URGENT R-6788 Inspected for plug, awaiting parts for repair.	Huntter Cannell
16/09/2024	163,013 kms 11,295 hrs	Electrical - IMPORTANT R-6817 See attached jobcard Replaced aerial, test ok.	Huntter Cannell
16/09/2024	163,013 kms 11,295 hrs	Cab R-6789 Awaiting mounts.	Huntter Cannell
16/09/2024	163,013 kms 11,295 hrs	Stereo R-6785 See attached jobcard UHF aerial replaced & tested.	Huntter Cannell
16/09/2024	163,013 kms 11,295 hrs	Windscreen/Mirrors - IMPORTANT R-6548 Front screen cracked. Done by CQ Machinery Glass.	Huntter Cannell
16/09/2024	163,013 kms 11,295 hrs	Engine R-6472 See attached jobcard Tighten engine mounts and top bracket.	Campbell Ferrington
16/09/2024	168,013 kms 11,295 hrs	Lights - IMPORTANT R-5761 See attached jobcard All lights work fine.	Campbell Ferrington
16/09/2024	163,013 kms 11,295 hrs	A - 15,000 S-4055	Huntter Cannell
05/09/2024	160,220 kms 11,252 hrs	Lights - IMPORTANT R-6745 See attached jobcard Lights & reflectors checked. Light bar seal, no signs of damage.	Huntter Cannell
20/08/2024	153,542 kms 11,138 hrs	Cab R-6164 See attached jobcard Door does lock with key.	Timothy McFadzen Contracting
20/08/2024	153,542 kms 11,138 hrs	Windscreen/Mirrors - IMPORTANT R-5762 See attached jobcard Wipers and washers work.	Timothy McFadzen Contracting
20/08/2024	153,542 kms 11,138 hrs	Lights - IMPORTANT R-5753 See attached jobcard Light bar still works.	Timothy McFadzen Contracting
20/08/2024		Driveline R-5752 See attached jobcard Chris Solomon replaced diff centres. With 2nd hand diffs / checked all ok.	Timothy McFadzen Contracting
20/08/2024	153,542 kms 11,138 hrs	Lights - IMPORTANT R-6246 See attached jobcard Repaired and replaced all lights as required. All lights now work.	Timothy McFadzen Contracting

Date	Reading / Units	Type / Repairer Notes	Repairer
20/08/2024		Brakes - URGENT R-6367 See attached jobcard Mick the truck driver fixed by putting wheel on bottom of it.	Timothy McFadzen Contracting
20/08/2024		Steering - URGENT R-6273 See attached jobcard Truck went to bigwheels.	Timothy McFadzen Contracting
15/05/2024	121,550 kms 10,584 hrs	Driveline R-5155 See attached jobcard Cleaned & inspected front & rear diffs from Dysart. Removed front diff centre & replaced. Removed & replaced rear diff centre & repaired. Replaced POS 4 hub seal due to leaking & replaced leaking drive stokes. Both second hand diff were fitted with new pinon seals.	Hayden Sluggett
13/05/2024	125,340 kms	Engine R-5152 See attached jobcard Cap has been fitted	Christopher Solmon
30/04/2024		Lights - IMPORTANT R-3112 See attached jobcard Repaired broken wiring for engine temp sensor & reverse lights. All other faults have been rectified.	ABC Automotive A/C & Electrical
29/04/2024	121,550 kms 10,584 hrs	A - 2 Wks S-3810 See attached jobcard Axle 2, RHS F, RHS R, Hub seals. No reverse lights (Repaired). Ad blue cap (Replaced). 3 rear stockies learning. Front drive & insput seal leaking. Ute mud guard damaged (Replaced). 3 out of 4 backing plates missing. Ice pack belts cracking. Horn not working. RHS window cracked.	Hayden Sluggett
23/04/2024		Lights - IMPORTANT R-5566 See attached jobcard Check & advise on faulty driving lights.	ABC Automotive A/C & Electrical
02/03/2024	101,153 kms	B - 30,000 S-3673 See attached jobcard	Lincoln Wild - LW Diesel & Contracting Services Pty Ltd
11/01/2024	91,246 kms 10,042 hrs	B - 35,000 S-3276 See attached jobcard Adjusted float tyres to 110psi, change u/s tyre, replace hubodometer Repair a/c replace dryer fix blown hose, replace leaking o-ringer Check over truck and trailer	Timothy McFadzen Contracting
03/01/2024	85,326 kms 9,934 hrs	Electrical - IMPORTANT R-3469 See attached jobcard Replaced heater core and pressure tested check for leaks Put rubbers under adblue tank Fitted black trailer release button and plumb up See attached jobcard Check over & repair speedo & diff temp fault Check engine oil temp fault - Fault not rectified (work ongoing)	Timothy McFadzen Contracting
01/11/2023	66,483 kms 9,588 hrs	A - 8 Wks S-2877 Wheels removed - P1 & P2 Date Retightened - P1 & P2 R/H door rubbing on top edge - adjusted hinge Eng Temp gauge N/W - replaced Rear shocks U/S - replaced Trailer plug casing broken - replaced Hi Beam inner L/H N/W - replaced both hi beam bulbs L/H Load Light N/W - To be completed by Corey No reverse lights or buzzer - to be completed by Corey L/H aerial broken - to be completed by Corey Engine temp wiring or sensor - to be completed by Corey	Robert Brackowski
12/09/2023		Other R-2570 See attached VDPH Job Form / Repairs	Internal Workshop
12/09/2023	47,258 kms 9,279 hrs	C - Annual S-2820 As per attached Service Jobcard S2820 Wheels Removed - Pos 1,2,5,6 - Changed Wipers - Fitted New King Pins to Pos 1 & 2 - Replaced Noisy A/c Pulley - Replaced gearshift cables - Replaced Pos 5 & 6 shoes & drums - Replaced Pos 1 & 2 steer tyres - Replaced Pos 6 shock absorber - Serviced Ice pack at 2,289hrs	
11/09/2023	47,258 kms	Asset Inspection Report - Final I-590	
06/09/2023		Asset Inspection Report - Initial I-589	

Signed: _____

Name: _____

Date: _____