



Vehicle History Summary



Fleet #	VD50
Registration	XQ03IU
Make	Western Star
Model	6900 FXC CONSTELLATION
VIN / Chassis #	5KKJABBG9KPKD5119
Build Date	2019

Date	Reading / Units	Type / Repairer Notes	Repairer
25/01/2026	40,830 kms 18,240 hrs	Bonnet R-11874 Removed high rise turntable turntable Original turntable fitted & tightened Pivot bearing snapped upon inspection assembly on RHS replaced	Huntter Cannell
11/08/2025	845,849 kms 18,172 hrs	Turntable - IMPORTANT R-10038 High rise turntable fitted inspection & trailer socket fitted ** Engine light - low air pressure to actuator & fluid pressure	Huntter Cannell
16/11/2024	842,980 kms	Brake Test 6 Months I-1716 Complete CapCoal CONEQU and brake test - VD69 50	Nick Fenton
06/11/2024	842,319 kms	Compliance, Turntable - IMPORTANT R-7394 Carried out hitching inspection. Inspected turntable mounting. Inspected turntable jaw kit. All operational.	Ryan Rosman - TMT Mechanical
06/11/2024		Turntable - Ringfeeder and Kingpin Inspection I-1698	Ryan Rosman
15/10/2024	842,971 kms	Hydraulics - IMPORTANT R-7083 Removed control box, welded up, refitted & tested	Peter Harris
15/10/2024	842,791 kms	B - 28000 S-5111 See attached jobcard	Handriaan Bashoff, Jonathan Rafferty - Misso, Peter Harris
13/10/2024		Fire Suppression Inspection I-1598 See attached inspection	Pyro Dynamics Pty Ltd
13/10/2024		Fire Extinguisher Inspection I-1597 See attached inspection	Pyro Dynamics Pty Ltd
10/10/2024	842,791 kms	Body, Chassis R-7080 Fab new bonnet mount and fit	Troy Francken
08/10/2024		Grease R-7081 See attached jobcard Grease and lubricate both trailer tarps. Adjust cables.	Timothy McFadzen
02/10/2024	840,120 kms	Air Conditioner R-7005 Other parts ordered Repaired plus on low pressure switch so clutch engages Wash dirt from evaporator & filters Remove rag from drivers side vent ducting locate flap to re-circulate air position (motor requires replacement)	east coast auto ele
02/10/2024	840,224 kms	Other R-7249 Hookup truck to trailers, repair tip control pilot airlines.	Timothy McFadzen
02/10/2024		First Aid Kit I-660 Kit unopened	Mark Matchett

Date	Reading / Units	Type / Repairer Notes	Repairer
30/09/2024		Tarp - IMPORTANT R-6957 See attached jobcard Can you cancel please as I will make jobcards for the trailers.	Internal Workshop
28/09/2024	834,621 kms	A - 14000 S-4977 See attached jobcard Grease Adjust clutch	Duane Hitch - Sourth East Mechanical
22/09/2024	834,800 kms	Lights - IMPORTANT R-6601 See attached jobcard Refer to repair order 6613	Liam Kitching - Misso
22/09/2024	834,800 kms	Lights - IMPORTANT R-6613 See attached jobcard Found plug had been cut on the pins, causes bad connection. Fit 4 pin detshu plug.	Liam Kitching - Misso
22/09/2024	835,442 kms	Leak - IMPORTANT R-6871 See attached jobcard Repaired air leak, loose hose. Refitted to joiner.	Ryan Rosman - TMT Mechanical
22/09/2024	835,442 kms	Electrical - IMPORTANT R-6666 See attached jobcard Inspected engine light on dash, found adblue fault. Flushed system, carried out dosing test. Restart components. engine lights cleared off dash.	Ryan Rosman - TMT Mechanical
22/09/2024	835,442 kms	Electrical - IMPORTANT R-6665 See attached jobcard Refer to R-6666 repair. Unit was in de-rate due to adblue fault.	Ryan Rosman - TMT Mechanical
22/09/2024	834,800 kms	A - 14000 S-4945 See attached jobcard	Daniel Farinha - Misso's
19/09/2024		Other R-7250 17/09/2024 Get snapped drain lock valve out Fit bung Adjust brakes 19/09/2024 Join broken tarp cable	Timothy McFadzen
04/09/2024		Breakdown R-6765 See attached breakdown Travelled from MVP MIA south to Copabella. One truck lost all air to dolly / hit rock and hit drain valve off bottom of tank. Easy out broken bit out, fit new drain valve, travel back to MVP MIA south.	Robert Brackowski
04/09/2024		Breakdown R-6766 See attached jobcard Travel from Beet Road to Coppabella, truck had no power. Checked turbo, was ok, air cleaners weren't too bad - found intake pipe off compressor, had movement, was loose - tightened it. (Would have had boost leak).	Robert Brackowski
16/08/2024	819,856 kms	Suspension - URGENT R-6281 See attached jobcard Removed & replaced front shackle pins & bushes.	Peter Harris, Ryan Rosman - TMT Mechanical
16/08/2024	819,856 kms	E - 336000 S-4436 See attached jobcard Oil leak / weeping from top RH gear cover - Fixed.	Harry Louis, Joseph Parker, Peter Harris, Ryan Rosman - TMT Mechanical
13/08/2024	819,856 kms	Electrical - IMPORTANT R-6544 See attached jobcard Inspected speedo fault. Replaced sensor, inspected ring & secured to sensor. Road tested, all operational.	Ryan Rosman - TMT Mechanical
13/08/2024	819,856 kms	Driveline R-6543 See attached jobcard R&R through shaft & housing, inspect bearings & re-seal & install.	Joseph Parker, Matthew Twitchett
13/08/2024	819,856 kms	Engine R-5544 See attached jobcard Sump gasket replaced & re-sealed @ time of E Service. Run up & tested.	Ryan Rosman - TMT Mechanical
13/08/2024	819,856 kms	Steering - URGENT R-6542 See attached jobcard Replaced king pins.	Peter Harris
13/08/2024		Breakdown R-6633 See attached jobcard Re-run power cable from tablet, power pack to tablet cradle as fuse box cover is broken. Checked tablet, was charging after repair.	Damian Ryan
10/08/2024	819,641 kms	Brake Test 6 Months I-1476	Damian Ryan

Date	Reading / Units	Type / Repairer Notes	Repairer
		See attached jobcard	
10/08/2024		Brake Test 6 Months I-1477	Damian Ryan
		See attached jobcard	
14/07/2024	819,856 kms	Engine R-6279	Daniel Farinha - Misso's
		See attached jobcard Replace engine mounts front & back.	
14/07/2024	819,856 kms	Steering - URGENT R-6280	Daniel Farinha - Misso's
		See attached jobcard Replace steering drag link.	
13/07/2024	819,856 kms	Intercooler R-6282	Daniel Farinha - Misso's
		See attached jobcard Replace intercooler and piping.	
13/07/2024	819,856 kms	Engine R-6284	Daniel Farinha - Misso's
		See attached jobcard Adjust valves and test.	
13/07/2024	819,856 kms	Brakes - URGENT, Suspension - URGENT R-6283	Daniel Farinha - Misso's
		See attached jobcard Fit new 4 way valve.	
11/07/2024	819,140 kms	Engine R-6262	Duane Hitch - Sourth East Mechanical
		See attached jobcard Top VP engine oil sltrs.	
11/07/2024	819,140 kms	Body R-6263	Troy Francken
		See attached jobcard Repair grill.	
02/07/2024	818,340 kms	Electrical - IMPORTANT R-6094	Daniel Farinha - Misso's, Harry Louis
		See attached jobcard Replaced windows regulator, tested - works good.	
25/06/2024	817,462 kms	Cab, Electrical - IMPORTANT R-6154	DBE Heavy Vehicle Repairs
		See attached jobcard Found wire burnt out in dash for red dot relay. Repaired wire and replaced red dot fans.	
20/06/2024	817,043 kms 17,283 hrs	Lights - IMPORTANT R-5759	Matthew Twitchett
		See attached jobcard	
20/06/2024	817,043 kms 17,283 hrs	Windscreen/Mirrors - IMPORTANT R-5760	Matthew Twitchett
		See attached jobcard	
08/06/2024	812,530 kms	A - 14000 S-4223	Jonathan Rafferty - Misso, Peter Harris
		See attached jobcard Bottom radiator hose clamp replaced. 1LT front diff oil. Adjusted turntable.	
06/06/2024	81,178 kms	Engine, Radiator - IMPORTANT R-5935	Peter Harris
		See attached jobcard Remove jewellery from R/H side of motor, remove bypass tube, pressure test, repair cracks, re-mount tube and adjust mounts as to not stress / twist tube, reassemble associated parts and test run.	
24/05/2024	880,330 kms	Brake Test 3 Months I-1222	Damian Ryan
		Complete IP 12W brake test - PASS	
16/05/2024	801,633 kms	Exhaust R-5630	Jonathan Rafferty - Misso
		See attached jobcard Found clip had broken off have connected to injector of exhaust. Banned itself against the exhaust. Removed hose from VD83 as a temporary fix to get VD50 running. Undergo dosage test & all worked fine. (Need to order in new hoses).	
16/05/2024	801,633 kms	Engine R-5573	Jonathan Rafferty - Misso
		See attached jobcard Disconnected Horton fan air supply to constantly cool down engine/radiator. Recommend replacing control solenoid to engage Horton fan.	
16/05/2024	802,027 kms	Lights - IMPORTANT R-5608	Jonathan Rafferty - Misso
		See attached jobcard Light working @ time of inspection.	
11/05/2024	799,174 kms	Engine R-5529	DBE Heavy Vehicle Repairs

Date	Reading / Units	Type / Repairer Notes	Repairer
		See attached jobcard Breakdown replace rail pressure sensor.	
10/05/2024	799,124 kms	Cab R-5439	Jonathan Rafferty - Misso
		See attached jobcard Handle to adjust seats was seized. Lubricated and worked handle and freed it. Works fine now.	
10/05/2024	799,142 kms	Body R-5512	Jonathan Rafferty - Misso
		See attached jobcard Mudguard bracket repaired.	
10/05/2024	799,112 kms	Engine, Radiator - IMPORTANT R-5334	Jonathan Rafferty - Misso
		See attached jobcard Clutch brake defect is repaired. Freed adjuster and adjusted clutch. Replaced Horton fan. Works fine now.	
10/05/2024	799,142 kms	B - 28000 S-4096	Jonathan Rafferty - Misso
		See attached jobcard	
04/05/2024	799,174 kms	Air Conditioner R-5528	DBE Heavy Vehicle Repairs
		See attached jobcard Breakdown Vitrinite. Repair has contact in blower muter plug.	
01/05/2024	794,790 kms	Brake Test MNM 3 Monthly I-1169	Gregory Fing
		Complete MBN work order and brake test - PASS	
30/04/2024	794,503 kms	Conneq Pre Inspection I-1126	Nick Fenton
		Complete CONEQU inspection and brake test - PASS	
28/04/2024	793,929 kms	Lights - IMPORTANT R-5407	Adam Wilson, Jonathan Rafferty - Misso
		See attached jobcard Remove & replace left and right load lights tested and all good.	
27/04/2024	793,929 hrs	Turntable - Ringfeeder and Kingpin Inspection I-1152	Jonathan Rafferty - Misso
		See attached inspection	
27/04/2024	793,929 kms	Turntable - IMPORTANT R-5401	Adam Wilson, Jonathan Rafferty - Misso
		See attached jobcard Completed turntable inspection.	
27/04/2024	793,979 kms	Hub Bearing - Urgent R-5414	Adam Wilson
		See attached jobcard Remove & replace #3 inner hub seal big clean up Tested all good no leaking.	
19/04/2024		Fire Suppression Inspection I-1197	Pyro Dynamics Pty Ltd
		See attached report System components in good condition. All system components lubricated and inspected. Clean clear passage completed, on ring-main & actuation circuits. Actuators and LOP valve head services.	
06/04/2024		MT Data R-5109	Damian Ryan
		See attached jobcard Load gearbox to tablet. Talk to support to get open IP tablets sent out. Send a new talon config sent out. Check talon works with gearbox.	
06/04/2024		Guardian R-4466	Damian Ryan
		See attached jobcard Canned out manual recording and plugged into unit all working correctly.	
02/04/2024	784,102 kms 16,504 hrs	A - 2 Wks S-3921	Adam Wilson
		See attached jobcard Front diff output shaft seal leaking Jump gasket leaking Front diff centre seal leaking Electrical issue tuck accessories still on with key off must isolate	
26/03/2024	782,326 kms	Lights - IMPORTANT R-4499	Daniel Breen - TMT
		See attached jobcard Cab wiring required overhaul, new harness installed. Route harness for marker lights required replacing as well. Interior was fully disassembled to run wiring.	
25/03/2024	782,326 kms	Engine, Turbo R-4929	Jonathan Rafferty - Misso
		See attached jobcard Fixed an oil leak at the top of the return hose. Couple days later was asked to check an oil leak on the turbo/exhaust side again. Found gromet seal going into the sump was leaking. Called Chris and told him it will be sent to the shed for repairs as I was already on site doing breakdowns. After Ryan & I finished repairing VD67 trailer set, we went and inspected VD50 again which pulled up between Saraji Mine and Vulcan. Found oil weeping out of the intercooler piping. Removed pipe work and found the turbo had failed.	

Date	Reading / Units	Type / Repairer Notes	Repairer
18/03/2024	781,671 kms	Engine, Radiator - IMPORTANT R-4498 See attached jobcard Installed new coolant pipe behind turbo New turbo gaskets oil return line gasket	Adam Wilson
18/03/2024	781,620 kms	Cab R-4467 See attached jobcard Installed new rubber boot.	Adam Wilson
18/03/2024		Turntable - Ringfeeder and Kingpin Inspection I-1026 See attached inspection report	Sione Lousi
18/03/2024		Engine R-3734 See attached jobcard Cleaned & inspected monitor to see if bad leak.	Christopher Solmon
18/03/2024		Engine R-3738 See attached jobcard Washed engine & monitor leak.	Christopher Solmon
18/03/2024	781,620 kms	Body R-4600 See attached jobcard Tested and inspect bonnet mounts. All ok.	Adam Wilson
17/03/2024	789,671 kms 164 hrs	A - 2 Wks S-3827 See attached jobcard Please order left bonnet blinker panel light 002123 part number	Adam Wilson
17/03/2024	781,671 kms 16,415 hrs	B - 30,000 S-3721 See attached jobcard Please order front left bonnet blinkers (panelite 002123 is current)	Adam Wilson
15/03/2024	780,886 kms	Wheels/Tyres - URGENT R-4808 See attached jobcard Replaced with 3 32mm wheel nuts	Jonathan Rafferty - Misso
12/03/2024	779,253 kms	Body R-4737 See attached jobcard Remove radiator support bracket and intake pipe for repair	Duane Hitch - Sourth East Mechanical
12/03/2024	779,253 kms	Lights - IMPORTANT R-4465 See attached jobcard No fault found at time of inspection.	Duane Hitch - Sourth East Mechanical
10/03/2024	778,264 kms	New, Retighten Wheels T-64 See attached jobcard Replaced all Drive tyres Carried out Re-torque	Duane Hitch - Sourth East Mechanical
07/03/2024	768,711 kms	MT Data R-4456 Refer 4601 for further comments	Nick Fenton
04/03/2024	776,536 kms	Body R-3737 See attached jobcard Had boil repair grill when truck was last in w/shop	Christopher Solmon
04/03/2024		Guardian R-4602	Global Installs
04/03/2024		MT Data R-4601 Carried out systems check on Mtdata all ok	Global Installs
01/03/2024	773,440 kms	Brake Test MNM 3 Monthly I-972 Complete Issac Plains Brake Test - PASS	Nick Fenton
28/02/2024	773,729 kms 16,237 hrs	Missing R-4468 See attached jobcard Replaced fuel fob	Christopher Solmon
28/02/2024	773,440 kms	Brake Test 3 Months I-971 See atched Brake Test - 3 Monthly	Gregory Fing
17/02/2024	768,708 kms 16,122 hrs	Electrical - IMPORTANT R-4448	Matthew Twitchett

Date	Reading / Units	Type / Repairer Notes	Repairer
		See attached jobcard Removed speed sensor & clean-reset. Timed up & restrain wiring R+R 2x clearance side lights Repair wiring & restrain	
16/02/2024	768,707 kms	A - 2 Wks S-3590 See attached jobcard	Daniel Breen - TMT
16/02/2024	767,863 kms	Air Conditioner R-4258 See attached jobcard Can not fault	Christopher Solmon
14/02/2024	768,707 kms	Cab R-3179 See attached jobcard Mats were removed and replaced	Daniel Breen - TMT
12/02/2024	768,707 kms	Engine R-3735 See attached jobcard Replaced with new part	Harry Louis
12/02/2024	78,757 hrs	Leak - IMPORTANT R-3391 See attached jobcard Engine getting swept out	Jonathan Rafferty - Misso
12/02/2024	765,875 kms	Windscreen/Mirrors - IMPORTANT R-4141 See attached jobcard Please order in part number - D3210 washer pump	Daniel Breen - TMT, Jonathan Rafferty - Misso
12/02/2024	768,707 kms	Cab R-2811 See attached jobcard Replaced seat belt	Jonathan Rafferty - Misso
10/02/2024	768,707 kms	Driveline, Transmission/Clutch - URGENT R-3178 See attached jobcard New cooler & bracket on	Daniel Breen - TMT
09/02/2024	767,863 kms	Wheels/Tyres - URGENT R-4256 See attached jobcard Replaced steer tyres - new	Daniel Breen - TMT
28/01/2024	16,053 hrs	D - 1000hr - Major S-3497 See attached jobcard	Nick Lockley
24/01/2024	15,978 hrs	E - Visual / Grease S-3582 See attached jobcard	Aiden Hawkins
19/01/2024		Communication System - URGENT, Other R-4160 See attached jobcard Fill Adblue Remove Capcoal radio	Todd Gunning - Optimal Diesel Support
18/01/2024		Other R-4159 See attached jobcard	Todd Gunning - Optimal Diesel Support
12/01/2024		Engine R-4078 See attached jobcard Replace fan belt tensioner	Nick Lockley
20/12/2023	748,828 kms	B - 35,000 S-3298 See attached jobcard 3298 Filter on left hand side broken - wo 3735 Driver side coolant leak - wo 3391 Ad blue leak driver side under cab - need more information PTO leak oil - replaced PTO Grill loose (chrome part) - note need parts brake down to source replacement - wo 3737 Oil weap around fuel pump - note need fuel pump mount face seal - wo 3738 Bonnet latch driver side - Replaced latch Fuel tank straps rubbers - replaced 2 x rubber tank straps Exhaust clamp @ turbo missing nut and was loose - found replacement nut and repaired Timing cover starting to leak - wo 3734 POS 5 J-bean nut come loose - tighten up j-beam Gear shift tower has excessive play, also needs isolator bush Diff oils burnt - replaced both diff oils, replaced diff filter, cleaned front diff screen	Daniel Farinha - Misso's
19/12/2023	748,828 kms	Hydraulics - IMPORTANT R-3177 See attached jobcard 3177 Remove and replace PTO, studs, oil and filter	Daniel Breen - TMT
19/12/2023	748,828 kms	Engine, Other, Transmission/Clutch - URGENT R-3176 See attached jobcard 3176 Grease nipple fitted + not needed	Daniel Breen - TMT
19/12/2023	748,828 kms	Driveline, Leak - IMPORTANT, Transmission/Clutch - URGENT R-3180	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		See attached jobcard 3180 Remove PTO pump, drain gearbox oil, remove and replace filter, remove PTO, remove studs, buff surface, install new studs, install slims and apply boctite 515 flango sealant. install PTO, install pump, test (good).	
19/12/2023	748,828 kms	Transmission/Clutch - URGENT R-3658	Daniel Breen - TMT
		See attached jobcard 3658 Clutch is hydraulic operated + has no free play	
19/12/2023		Leak - IMPORTANT R-3246	Christopher Solmon
		See attached jobcard 3246 Timing cover / balancer seal starting to leak. Need to order seal kit, make up new w/o to repair Eng no: 80034225 15X15E5	
19/12/2023	748,828 kms	Lights - IMPORTANT R-3175	Internal Workshop
		See attached jobcard 3175 Inspected all lights and can not fault light	
18/12/2023		Engine, Fuel R-3696	Internal Workshop
		See attached jobcard 3696 Fuel tank 1/4 full found e-stop in cab pushed (cuts fuel solenoid)	
12/12/2023		Transmission/Clutch - URGENT R-3565	Internal Workshop
		See attached jobcard 3565 Lock nut was taken from rivet truck New nut must be ordered Vehicle met me at EME pad near vulcan mine whilst other repairs were taken place on VD98 and Kenworth 909	
08/12/2023	745,115 hrs	Brake Test Annual I-698	Nick Fenton
		See attached Brake Test Report	
06/12/2023		Communication System - URGENT R-2745	Internal Workshop
		Waiting for Todd from Ritson Auto Electrician to visit site 06/12/2023 - Todd from Ritson Auto Electrician visited site. Todd called to say that he could no see any issues with the tablet. Close Ticket	
06/12/2023		Engine R-3505	Daniel Breen - TMT
		See attached jobcard Front timing cover weeping Power Steering pump Rad leaving from core Corss over pipe leaking	
29/11/2023		Communication System - URGENT R-2747	Tina O'Hare
		Refer Repair Jobcard R2745 (duplicate entry)	
27/11/2023	739,669 kms	Lights - IMPORTANT R-3446	Internal Workshop
		See attached jobcard 3446 Repaired wiring on rear of truck	
23/11/2023	738,806 kms	A - 8 Wks S-3167	Internal Workshop
		A Service and CONEQU check over before the CONEQU inspection See attached service jobcard 3167 Beacon switch faulty - replaced Roof clearance light not working Bonnet L/H indicator not working - repaired Safety triangles broken - replaced Coolant leak on pipe R/H side infront of turbo - W/o created 3391 PTO oil leak - W/O done needs parts 3177 L/H mirror LED not working - parts on order Diff cooler disconnected - parts on order 3178 Front cab mounts - parts in constock - w/o done 3179 1st drive diff seals leaking Driver's seat belt frayed Rear mud flaps damaged - replaced both	
23/11/2023	738,906 kms	King Pin - IMPORTANT, Turntable - IMPORTANT R-3347	Internal Workshop
		See attached jobcard 3347 Turntable + jaws inspected, new and in good condition	
23/11/2023	738,906 kms	Electrical - IMPORTANT R-2939	Internal Workshop
		See attached jobcard 2939 Faulty switch Advise Supervisor of findings - waiting parts Replaced beacon light switch	
17/11/2023		Air Conditioner R-3317	Internal Workshop
		See attached jobcard 3317 Tested and spoke to day shift driver, a/c is working	
17/11/2023		Transmission/Clutch - URGENT R-3279	Internal Workshop
		See attached jobcard 3279 Tightened gear knob	
06/11/2023		Leak - IMPORTANT R-2353	Internal Workshop
		See attached jobcard 2353 Repairs to be completed at B service (next service) Replaced 2 x leaking fuels hoses 14/10mt All faults repaired	
06/11/2023	725,631 kms	Engine R-3012	Internal Workshop
		See attached jobcard 3012 Repair steel pipe and replace o rings and gasket	
06/11/2023		A - 8 Wks S-3071	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		See attached jobcard 3071 Rear amber reflectors broken / missing Back of truck above 2nd diff hoses and wires loose missing reflector LHR - Fit new reflector Front left indicator not working - Repair temporarily needs new light Side mirror park light not working - good - order parts - W/O created 3175 Side park light ynder passenger door dim - order parts - W/O created 3175 Throw out bearing, grease line not connected - W/O make up grease line for Gear box - W/O created 3176 PTO leaking - W/O replace PTO - W/O created 3177 Exhaust cracked in let to cat leaking add blue Diff cooler cracked (tag out) - by passed need to order new cooler - W/O created 3178 POS 3, 5 S arm bushes Drive brake grease lines not connected - manually greased needs to be reconnected Front cab mounts sagged - W/O replace cab mounts 3179 Drive tyres need replacing - replaced drive tyres Diff input seal starting to leak 1st diff - W/O replace diff input seal - W/O created 3180 1st diff out put seal leaking - W/O replace diff out put seal - W/O created 3180 PTO by passing oil - as above W/O created 3180	
06/11/2023	725,631 kms	Electrical - IMPORTANT R-2916 See attached jobcard 2916 Was caused by low coolant from leaking pipe which has been repaired	Internal Workshop
06/11/2023	725,631 kms	Suspension - URGENT R-2860 See attached jobcard 2860 Bar not bent	Internal Workshop
03/11/2023		Lights - IMPORTANT R-2940 See attached jobcard Advice supervisor of findings Couldn't fault, working at time of inspection	Joseph Celetaria
29/10/2023	725,543 kms	Brake Test Annual I-850 See attached report	Nick Fenton
27/10/2023		Cab R-2915 See attached jobcard 2915 Advice supervisor of findings Give motor tap to make it work for the mean time Replaced blower fan	Joseph Celetaria
27/10/2023		Air Conditioner R-2941 See attached jobcard 2941 Advice Supervisor of findings. Repaired by cleaning condensor	Internal Workshop, Joseph Celetaria
27/10/2023	721,180 kms	Air Conditioner R-3020 See attached jobcard 3020 Clean evaporator and replace fan Job has been done	Internal Workshop
17/10/2023	715,566 kms	B - 35,000 S-3011 See attached jobcard Resealed leaking PTO Tightened MYD Fittings off pump pressure - relief Replaced & cleaned leaking Pos 5 hub seal	Matthew Twitchett
29/09/2023		Other R-2775 See attached repair job card 2775 Fitted second hand road train signage to rear trailer	Internal Workshop
28/09/2023		Other R-2225 Inspected - all operational no fault found	Ryan Rosman - TMT Mechanical
28/09/2023	708,285 kms	A - 8 Wks S-2868 A Service - See attached service job card 2868 Front cover rubber plug weeping - ok parts required P/S pressure hose rubbing - re-positioned Radiator tanks weeping coolant -plan repair Water pump outlet crossover pipe o-rings weeping - require parts Front spring shackle busted and pins worn - excessive wear - pin keepers sliding on pins - source parts & plan repair Air filter caps in wrong position - rotated caps, inspected air filters PTO cartridge weeping oil - requires cartridge gasket, topped up level Oil weeping from breather hose - monitor condition Engine breathing higher than normal Fuel lines weeping - plan with hose maker at B service Hydraulic diverter valve weeping oil - plan repair at B service J beam pivot busted beginning to crack and peel - monitor, source parts and plan repair Cab mounts showing signs of wear - monitor next service POS 3 J beam trunion nut loose - safety tab in place No suzi coils fitted - R&R brake hose to suzi coils Rear mud flaps split - change out at B service Diff plugs worn out - require new plugs fill and drain	Internal Workshop
28/09/2023		Wipers - IMPORTANT R-2241 Drivers wiper all ok	Ryan Rosman - TMT Mechanical
21/09/2023		Lights - IMPORTANT R-2659 See attached repair job card 2659 Service call to Vulcan mine and return Attend to complaint of tail light on dolly not working Carry out test, locate cause to short circuit on back left clearance light, wires are burnt, run new cable from left to centre back of dolly and connect wires, test ok Drill small hole to drain water inside tail light enclosure to prevent damage from reoccurring	Internal Workshop
15/09/2023		Electrical - IMPORTANT R-2632	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		See attached breakdown job card 2632 Breakdown to Vulcan Mine - Service call to Vulcan Mine and return Attend to complaint of vehicle E stop button broken R & R E stop button and check ok Attend to complaint of vehicle not starting, carry out necessary checks, locate cause to faulty start relay engine bay fuse box, remove & replace and check ok	
15/09/2023		Lights - IMPORTANT R-2633	Internal Workshop
		See attached breakdown job card 2633 Service call to Vulcan Mine and return Twice Attend to complaint of no lights on trailer, carry out test, locate cause to volt drop on dog trailer, rewire front of trailer and change plugs, test ok We might need to check other trailers for future rewire since volt drop is common for long trailers and found out junction boxes have quick connectors that are not good because they create volt drop on the joints	
14/09/2023	700,390 kms	A - 8 Wks S-2753	Internal Workshop
		See attached service job card 2753 PTO Cartridge weeping oil - Gearbox level ok Diverter valve fitting weeping POS 4 Hub seal leaking - Repaired Gear train cover leaking oil Rear mudflaps Movement in turntable - inspect further - Repaired J Beam pivots bushers beginning to crack and peel out POS 5 J Beam Trunion nut loose - bush worn (slight movement in bushes) Bonnet grill u/s - required new part ASAP - Repaired Radiator top tank weeping Air cleaner top hats in wrong position Wiper blades u/s	
12/09/2023	700,392 kms	Compliance R-2573	Internal Workshop
		Confirmation of speed limited vehicle - VD50 Speed limited to 87kmph	
12/09/2023	700,392 kms	Compliance R-2588	
		System audit confirms both are in working order	
30/08/2023		Engine R-2489	Jospeh Celetaria
		Locate faulty starter - remove and replace starter solenoid **Batteries are a bit lazy	
29/08/2023	700,390 kms	Lights - IMPORTANT R-2379	Internal Workshop
29/08/2023	700,390 kms	Lights - IMPORTANT R-2414	Internal Workshop
29/08/2023	681,443 kms	Lights - IMPORTANT R-2209	Internal Workshop
		Repair and rewire RH low beam Replace and rewire white Clearence light (ST19)	
27/08/2023		Electrical - IMPORTANT, Lights - IMPORTANT R-2465	Internal Workshop
		Rewire loom to head lights, rewire spot lights, rewire right loom to headlights Tidy up wiring LHS behind headlight Rewire spotlights, indicator and LED bar lights	
14/08/2023	690,983 kms	Compliance R-2249	Internal Workshop
		Replaced with new	
14/08/2023	690,983 kms 14,181 hrs	B - 35,000 S-2650	Internal Workshop
		B service carried out as per service record - RK/CS Repaired wirring and replaced relay Unblocked jets, Adjusted wipers and jets fixed leak Replaced steer tyres Repaired air leak - found rubber hose for cab air bag Replaced fitter, pressure test system - coolant fitting Replaced bolt in cab stabilizer arms Adjusted ride height Replaced front engine mounts Tighten yolk nut - marked with paint pen Broken wire replacced up to mudguard to RH bullbar blinker Repaired mounting clamp plate for RH lower tank step	
14/08/2023	690,983 kms	Electrical - IMPORTANT R-1965	Internal Workshop
		Tested OK - Speed sensor replaced - RK	
14/08/2023	690,983 kms	Other R-2179	Internal Workshop
		Fitted new rubber nack under tarp strap	
14/08/2023		Other R-2303	Internal Workshop
		Repaired mudflap	
14/08/2023		Battery - IMPORTANT, Engine R-2305	Internal Workshop
		Could not fault at time of inspection	
14/08/2023	690,983 kms	Wheels/Tyres - URGENT R-2352	Internal Workshop
		New steer tyres fitted - DH	
13/08/2023	684,508 kms	Lights - IMPORTANT R-2226	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		Broken wire - Replaced	
13/08/2023		Wheels/Tyres - URGENT R-2178	Internal Workshop
		Replaced in service 13.08.2023	
10/08/2023	690,746 kms	Lights - IMPORTANT R-2310	Internal Workshop
		Could not fault at time of inspection - Checked all lights	
09/08/2023		Fire Suppression - IMPORTANT R-2307	Pyro Dynamics Pty Ltd
		Description of Works Completed: Yearly service carried out Checked operation of piston in head System in perfect condition Service extinguisher on trailer JOB COMPLETE Parts Used: 3x 9kg extinguisher bags 1x 4.5kg extinguisher bag 6x secure ties	
19/07/2023	675,338 kms	Lights - IMPORTANT R-2188	Duane Hitch - Sourth East Mechanical
		Repair RHS Head light wiring	
18/07/2023		Engine R-2132	Lincoln Wild - LW Diesel & Contracting Services Pty Ltd
		Engine won't start, check wiring, found bad connection at start ecm relay in engine bay. Repair connection, start engine. check over and pack up	
17/07/2023		Lights - IMPORTANT R-2011	Randall Kruger - ADS
		Repaired all faults	
17/07/2023		Lights - IMPORTANT R-2018	Duane Hitch - Sourth East Mechanical
		Replaced fuse	
17/07/2023		Transmission/Clutch - URGENT R-2026	Duane Hitch - Sourth East Mechanical
		Tightened gear knob	
17/07/2023		Electrical - IMPORTANT R-2027	Duane Hitch - Sourth East Mechanical
		Repaired	
17/07/2023	673,734 kms	A - 8 Wks S-2535	Duane Hitch - Sourth East Mechanical
		A Service carried out as per service report No cab interior lights - Replaced missing fuse Gear stick loose - tightened LHS side light not working - Repair wiring Engine / Transmission mounts - Replaced trans mounts Front mud flaps on bonnet - Fitted new bolts Hydraulic oil leak Diverter valve - Monitor DH Front grill broken - Glued Grill Fire system out of date - Booked Pyro Dynamics Thurs 20.07.23	
12/07/2023		Communication System - URGENT R-2099	Christopher Solmon
		Fit mine radio to truck. changed mounting location due to broken plastic and would not hold.	
08/07/2023		Communication System - URGENT R-1921	Hugh Middleton VDPH Maintenance Coordinator
		Check 2way unable to fault Ok	
08/07/2023		Tarp - IMPORTANT R-1922	Hugh Middleton VDPH Maintenance Coordinator
		Renew tarp and secure to LH of bin	
24/06/2023	663,646 kms	Transmission/Clutch - URGENT R-1865	Andrew Rooke - Helical Diesel
		22.06.23 - Disconnected from trailers - Put on hoists and began to remove hardware for clutch replacement. 23.06.23 - Remove gearbox / replace clutch and flywheel - reused engine mounts. 24.06.23 - Finished putting external hardware back on after clutch install. Fitted new clutch master cylinder and bottom engine mounts	
23/06/2023	663,644 kms	Electrical - IMPORTANT R-1720	Hugh Middleton VDPH Maintenance Coordinator
		New coolant switch	
21/06/2023		Electrical - IMPORTANT R-1814	Raw Auto Electrical
		Removed and Replaced Anderson plugs Inspect water level sensor, Found connector ordered incorrect. Make connector to suit. Heat shrink wiring and Re-test Ok	

Date	Reading / Units	Type / Repairer Notes	Repairer
20/06/2023	663,644 kms 13,592 hrs	A - 8 Wks S-2357 A Service carried out as per service report LH Indicator fault - RAW Repaired LH Bullbar indicator lense broken - Replaced R.R Air leak LH chassis rail behind gearbox R.R Top up hub oils R.R Interior lights not working - RAW repaired HM Clutch operation faulty - requires new master siave and clutch kit - New clutch fitted and master siave HM RH washer jet blocked R.R Door hinges binding R.R Front mudflaps R.R Exhaust stalks not straight - Repaired R.R Extinghiser bags R.R Oil pressure sensor - Replaced R.R Coolant level sensor leaking - Replaced sensor R.R - RAW replaced plug kit PTO extension housing to casing R.R Engine / Gearbox mounts worn and weeping - Remove and replace gasket and oil R.R Hydraulic leak at diverter valve - Monitor Diff oils burnt - Drained and replaced R.R Bonnet cracked on LH side - S/able HM Bonnet LH chrome trim unsecure - Secured HM Bonnet pivots worn / have movement - S/able HM Adblue leak near injector - Repaired R.R Pos 4 booster leaking - Replaced R.R Ride height out of adjustment - Adjusted and tested R.R Adjust turntable HM	Hugh Middleton VDPH Maintenance Coordinator , Ryan Rosman - TMT Mechanical
17/06/2023		Damage R-1674 Hugh Fitted steering wheel cover	Hugh Middleton VDPH Maintenance Coordinator , Randall Kruger - ADS
10/06/2023		Damage R-1721 Serviceable - bent back to stop it catching on door	Hugh Middleton VDPH Maintenance Coordinator
07/06/2023		Other R-1737 Reported large bang noise like tyre exploded - Checked all tyres, None flat or damaged. Checked Truck airbags, boost hoses, coolant pipes and found no fault. Sent to work.	Randall Kruger - ADS
28/05/2023	650,083 kms 13,332 hrs	B - 35000 S-2261 B Service carried out as per service report Grill loose and cracking, RH washer nozzle blocked. Ticked Alternator bearing noisy - New Alternator fitted - D.E	Hugh Middleton VDPH Maintenance Coordinator
28/05/2023	650,083 kms	Leak - IMPORTANT R-1441 Removed and Replaced Gasket, Weld pipe and coolant sensor - Completed at Service: S2261	Internal Workshop
26/05/2023	647,851 kms	Leak - IMPORTANT R-1664 Replaced Drive airbag 2nd axle LH side leaking.	Randall Kruger - ADS
24/05/2023		Communication System - URGENT R-1574 Driver reconnect tablet and was able to successfully log in,	Internal Workshop
21/05/2023		Leak - IMPORTANT R-1603 Repaired air leak on rubbed through hose - Checked boosters for leaks	Internal Workshop
20/05/2023		Damage R-1594 Repair Front grill, bolts have broken and it will need a new grill	Duane Hitch - Sourth East Mechanical
15/05/2023		Electrical - IMPORTANT R-1516 All lighting repairs carried out. Repair headlight interior light replace fuse had been removed.	Hugh Middleton VDPH Maintenance Coordinator , Randall Kruger - ADS
08/05/2023	631,754 kms 12,967 hrs	Transmission/Clutch - URGENT R-1505 Clutch fault - Repaired and bled clutch Check over and repair trailer tipping fault Replace trailer fittings	Randall Kruger - ADS
02/05/2023	630,657 kms 12,943 hrs	A - 8 Wks S-1993 A Service carried out as per service report Coolant leak - Parts ordered - Turned into a repair Hydraulic tank breather missing - Replaced JH Cab lights not working - Replaced fuse JH Adblue leaking from downpipe - turned into a repair Auto greaser fallen off - Fitted new bolts JH Hydraulic oil low - Topped up 65L - JH	ATL Diesel Services - Jordan Hasenkam
02/05/2023		Wheels/Tyres - URGENT R-1410 Replaced Front steers	Internal Workshop
02/05/2023		Wheels/Tyres - URGENT R-1413 Replaced all drive tyres	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
02/05/2023		Lights - IMPORTANT R-1394 Check All Healight and spot lights, Bar lights - No fault found - OK	Raw Auto Electrical
02/05/2023		Lights - IMPORTANT R-1394 Inspect and test interior light fault. Found open circuit wiring to light. Locate and repair, Test OK	Raw Auto Electrical
27/04/2023	627,169 kms 12,882 hrs	Leak - IMPORTANT R-1400 Truck not building up air - Found GOV valve u/s - went back to workshop, Pick up part and fit to truck. Tested all okay	ATL Diesel Services - Jordan Hasenkam
24/04/2023		Electrical - IMPORTANT R-1371 Adjust G/box speed sensor and tighten pins	Internal Workshop
22/04/2023	621,452 kms 12,772 hrs	Lights - IMPORTANT R-1328 Inspected lights are operational and Ok	Internal Workshop
22/04/2023		Electrical - IMPORTANT R-1302 Found sensor pushed out - Reset tested Okay	ATL Diesel Services - Jordan Hasenkam
21/04/2023		Lights - IMPORTANT R-1347 Checked and found 2 broken wires behind RH headlight - Repaired Checked and Found 1 broken wire on LH headlight - Repaired	Randall Kruger - ADS
19/04/2023		Electrical - IMPORTANT R-1303 Reset speedo sensor air gap	Internal Workshop
19/04/2023		Other R-1299 LH bonnet indicator N/W - Replaced LH bonnet indicator bulb Auto greaser needs new bowl / cracking - No fault found on auto greaser Coolant leak radiator and side pipe - Replaced Compressor Interior light N/W - Repaired 18/04/23 Randall	Hugh Middleton VDPH Maintenance Coordinator , Randall Kruger - ADS
18/04/2023	618,777 kms	Electrical - IMPORTANT R-1233 Repaired - Rewiring short in upper console blowing fuse.	Randall Kruger - ADS
17/04/2023		Other R-1151 Remove and Replace Compressor - Not Needed Air compressor was misdiagnosed.	ATL Diesel Services - Jordan Hasenkam
16/04/2023	617,426 kms 12,696 hrs	Leak - IMPORTANT R-1274 Traveled to Volcun and topped up coolant	Nick Fenton
14/04/2023	612,935 kms	Communication System - URGENT R-1226 Technician repaired aerial	Internal Workshop
14/04/2023	616,938 kms	B - 35000 S-2038 B Service carried out as per service report Wiper blades u/s - Ticked RB Coolant leak radiator and side pipes - Turn into a repair and order parts LH bonnet indicator n/w - Ticked RB Steering wheel leather peeling - Monitor Auto greaser needs new bowl/cracking - Turn into a repair and order parts P clamp broken cooling line - Ticked RB Trailer valve at firewall exhaust - Ticked RB Interior light n/w - Book with Raw Electrical Engine light on - Ticked RB	Rob Brackowski - Callcorr
08/04/2023	610,658 kms	Electrical - IMPORTANT R-1246 Clean speed sensor and check trans oil - Level monitor fault	Duane Hitch - Sourth East Mechanical
28/03/2023		Communication System - URGENT R-1162 As per attached report - Followed testing procedures and tested ok.	Mobile Tracking and Data Pty Ltd (MTData)
28/03/2023	600,407 kms	Engine R-1164 Found fan belt snapped, Checked all tensioners and pulleys - Fitted new belt and tested.	ATL Diesel Services - Jordan Hasenkam

Date	Reading / Units	Type / Repairer Notes	Repairer
27/03/2023	599,353 kms 12,351 hrs	A - 8 Wks S-1939 A Service Carried out as per service report. Alto greaser - Done Air leak at adblue pump - Done Cab mounts - Done Turn table feet - Done Coolant Pressurized - Requires new compressor - Part Ordered 27.03.23 Rebook to repair 10.03.23	ATL Diesel Services - Jordan Hasenkam
23/03/2023	593,278 kms 12,241 hrs	Lights - IMPORTANT R-1096 Replaced broken wire to lamp	Hugh Middleton VDPH Maintenance Coordinator
22/03/2023	593,908 kms 12,253 hrs	Leak - IMPORTANT R-1098 Repair pipe and tested Ok	Hugh Middleton VDPH Maintenance Coordinator
22/03/2023	593,908 kms 12,253 hrs	Communication System - URGENT R-1097 Driver Error in Operation of Two-way	Hugh Middleton VDPH Maintenance Coordinator
21/03/2023		Electrical - IMPORTANT R-1075 Inspected and No repair required	Hugh Middleton VDPH Maintenance Coordinator
20/03/2023	591,527 kms	Brakes - URGENT R-1076 Replaced LHR Booster	ATL Diesel Services - Jordan Hasenkam
20/03/2023	592,077 kms	Air Conditioner R-1077 Repair open circuit wiring at pressure switch. test operation - All ok	Raw Auto Electrical
20/03/2023	592,077 kms	Lights - IMPORTANT R-1074 Repair open circuit wiring and retest - all ok	Raw Auto Electrical
19/03/2023		Brakes - URGENT, Other, Wheels/Tyres - URGENT R-1102 Jack up truck, Remove tyres, Change air bag, cage up booster and refit tyres	ATL Diesel Services - Jordan Hasenkam
15/03/2023	586,647 kms 12,111 hrs	Electrical - IMPORTANT R-1047 Driver Error - switch un-operational	Hugh Middleton VDPH Maintenance Coordinator
13/03/2023	585,466 kms	A - 8 Wks S-1854 A service carried out as per service report Coolant leaks around radiator - Minor washed off Gearbox oil leak - no fluid in box - Replaced filter and oil Suspension arm bolts loose - tightened Interior lights not working - Relay and fuse ok - wiring fault for sparky	Randall Kruger - ADS
06/03/2023	577,616 kms 11,941 hrs	Cab, Damage R-996 been broken for a while, does not effect operational of the vehicle.	
04/03/2023	577,616 kms 11,941 hrs	BULLBAR R-997 Remove xs steel and Ally from carrier for bullbar	Hugh Middleton VDPH Maintenance Coordinator
03/03/2023	576,474 kms 11,920 hrs	Leak - IMPORTANT R-993 Found to pressurized wrong header tank - cap replaced	Hugh Middleton VDPH Maintenance Coordinator
23/02/2023	569,396 kms 11,794 hrs	B - 35000 S-1763 Changed rear air bag - fixed Need steer tyres spun on rim - Serviceable will be done next service Need tank bracket welded - repaired need air fitting for adblue pump - New coupling - noted Awaiting parts - be done next service coolant leaks - Slight leak S/able Needs cab mounts - New mounts Fitted Auto greaser line broken - Fixed	ATL Diesel Services - Jordan Hasenkam
23/02/2023	569,396 kms 11,794 hrs	Leak - IMPORTANT R-913	Hugh Middleton VDPH Maintenance Coordinator

Date	Reading / Units	Type / Repairer Notes	Repairer
		Replaced RH 3rd axle Air bag	
20/02/2023	567,098 kms	Lights - IMPORTANT R-933 Found broken wire - Rejoined tested okay	ATL Diesel Services - Jordan Hasenkam
20/02/2023	567,098 kms	Leak - IMPORTANT R-932 Topped up Coolant Checked cap - all okay Sight glass - all okay No Repairs required	ATL Diesel Services - Jordan Hasenkam
20/02/2023	567,098 kms	Damage R-935 Truck still starts no repair required	ATL Diesel Services - Jordan Hasenkam
20/02/2023	567,098 kms	Cab R-936 Checked and okay - No repair required	ATL Diesel Services - Jordan Hasenkam
19/02/2023		Air Conditioner R-893 A/c relay replaced. New starter motor	Internal Workshop
11/02/2023	552,954 kms 11,452 hrs	Lights - IMPORTANT R-871 repairs carried out on service 11/02/23	Hugh Middleton VDPH Maintenance Coordinator
11/02/2023		Damage R-887 repaired superficial damage plate and weld	Hugh Middleton VDPH Maintenance Coordinator
11/02/2023	557,941 kms 11,564 hrs	A - 8 Wks S-1550 As per Service Report	Randall Kruger - ADS
28/01/2023	548,524 kms 11,363 hrs	A - 8 Wks S-1590 As per Service Report	Randall Kruger - ADS
13/01/2023	540,866 kms 11,208 hrs	A - 8 Wks S-1514	ATL Diesel Services - Jordan Hasenkam
04/01/2023	534,938 kms 11,099 hrs	Lights - IMPORTANT R-784 rewire suzy	Hugh Middleton VDPH Maintenance Coordinator
03/01/2023	534,886 kms 11,097 hrs	B - 35000 S-1470 Faulty slack adjuster 3rd axle R/H side Air leak in chassis L/H side Faulty slack adjuster 1st axle R/H side - parts on order Exhaust leak at flex turbo side - New gasket Coolant sensor in header tank faulty Slack adj on back order from United States	Randall Kruger - ADS
30/12/2022		Air Conditioner R-571 REPAIR carried out by RAW ON JOB 643	Hugh Middleton VDPH Maintenance Coordinator
22/12/2022		Engine R-769 checked on road test jake working on al stages nff	Hugh Middleton VDPH Maintenance Coordinator
22/12/2022	530,802 kms 10,990 hrs	Lights - IMPORTANT R-770 replace spotlight relay and repair marker light	Hugh Middleton VDPH Maintenance Coordinator
21/12/2022	529,666 kms 10,969 hrs	Lights - IMPORTANT R-767 broken wire repaired	Hugh Middleton VDPH Maintenance Coordinator
17/12/2022	525,428 kms 10,886 hrs	C - Annual S-1424	Hugh Middleton VDPH Maintenance Coordinator

Date	Reading / Units	Type / Repairer Notes	Repairer
		C Serv all hub + diff oil change Overhaul rear suspension Overhaul acc scams & Bushs New steer tyres fitted & balanced rings Raplce x 4 rear shocks	
29/11/2022		Air Conditioner R-527 repair carried out by RAW AUTO ELETRICAL	Hugh Middleton VDPH Maintenance Coordinator
13/11/2022	505,408 kms 10,511 hrs	A - 8 Wks S-1310 pas leave at pressure hose to RH steer box oil leak at PTO to pump hose repaird hyd oil leak at pressure hose to dvt front steering alinment adjusted rear axle beams require retorque high beam inop new switch control fitted screen wash inop - pump wiring	Hugh Middleton VDPH Maintenance Coordinator
11/11/2022		Lights - IMPORTANT R-638 renew switch	Hugh Middleton VDPH Maintenance Coordinator
07/11/2022	500,918 kms	Brake Test Annual I-413 CC Brake Test - PASS	Nick Fenton
31/10/2022		Fire Extinguisher Inspection I-547	Internal Workshop
31/10/2022		Fire Extinguisher Inspection I-553	Internal Workshop
31/10/2022	499,735 kms	Brake Test Annual I-407 MNM Brake Test - PASS	Gregory Fing
31/10/2022		Fire Extinguisher Inspection I-514	Internal Workshop
28/10/2022		Other R-610 driver shown how to operate the jake brake	Hugh Middleton VDPH Maintenance Coordinator
19/10/2022	499,584 kms 10,304 hrs	Other R-526 Replaced on service S1179	Jones Diesel Maintenance Services - Andy Jones, Nick Fenton
19/10/2022	499,584 kms 10,304 hrs	B - 35000 S-1179 Adblue cap broken - New cap LH tie rod end ball join worn latrall - New Whool chock missing - Replaced Bull bar bolts missing - Replaced Front gill insecure - Secured RH 1st drive brake shoes roller missing - Replaced 1st diff stanvore mounting broken from diff	Hugh Middleton VDPH Maintenance Coordinator
12/10/2022		Chassis R-494	Jones Diesel Maintenance Services - Andy Jones, Nick Fenton
03/10/2022		Other R-538	Jones Diesel Maintenance Services - Andy Jones, Nick Fenton
19/09/2022	485,380 kms 9,861 hrs	B - 35000 S-1078 CHECK ENG LIGHT ABS FAULT' L/H MUD FLAP TOP BONNET MOUNT BROKEN LOWER BONNET MOUNT BROKEN COOLANT SENSOR BROKERN - NEW SENSOR (R515) BONNET SPRING BROKEN GEAR BOX OIL LOW	ATL Diesel Services - Jordan Hasenkam
19/09/2022	485,380 kms 9,861 hrs	Electrical - IMPORTANT R-515 Repaired on S1078	Jones Diesel Maintenance Services - Andy Jones, Nick Fenton
07/09/2022		Windscreen/Mirrors - IMPORTANT R-493	Jones Diesel Maintenance Services - Andy Jones, Nick Fenton
27/08/2022	475,426 kms 9,572 hrs	C - Annual S-1027	ATL Diesel Services - Jordan Hasenkam

Date	Reading / Units	Type / Repairer Notes	Repairer
		Right rear tail lights out Hole in exhaust Need drive tyres	
17/08/2022		Lights - IMPORTANT R-463 Jones Diesel Maintenance Services - Andy Jones, Nick Fenton	
17/08/2022		Lights - IMPORTANT R-464 Jones Diesel Maintenance Services - Andy Jones, Nick Fenton	
09/08/2022		Brake Test Annual I-293 PASS - For MNM Gregory Fing	
31/07/2022		Fire Extinguisher Inspection I-481 Internal Workshop	
26/07/2022		Air Conditioner R-380 Hugh Middleton VDPH Maintenance Coordinator regas and replace leaking hose	
26/07/2022		Lights - IMPORTANT R-381 Hugh Middleton VDPH Maintenance Coordinator replaced lamp	
26/07/2022	457,773 kms 9,112 hrs	Other R-382 Hugh Middleton VDPH Maintenance Coordinator replaced all bolt in bull bar	
26/07/2022	457,773 kms 9,112 hrs	B - 35000 S-935 Hugh Middleton VDPH Maintenance Coordinator COOLANT LEVEL SWITCH DAMAGED - REPLACED ADBLU VENT BLOCKED - CLEARED VENT LOWER CROSSBAR BOLTS LOOSE - RETORQUED FRONT BULLBAR MOUNT BOLT BROKEN - REPLACED	
23/07/2022	455,036 kms 9,026 hrs	A - 8 Wks S-924 Hugh Middleton VDPH Maintenance Coordinator FRONT GRILL INSECURE - SECURED WITH FIBRERUST FRONT CROSSOVER BAR AT FLYWHEEL HOUSE LOOSE CLUTCH ADJUSTED AIR LEAK AT 1st DRIVE - AIR BAGS REPLACED **CLUTCH STARTING TO FAIL. ADVISE AT NEXT SERVICE	
30/06/2022		Fire Extinguisher Inspection I-409 Internal Workshop As per service sheet	
15/06/2022	439,031 kms 8,646 hrs	B - 35000 S-827 Nick Fenton Replace rear left hand air bag (leaking) Replace fire extinguisher	
08/06/2022		Air Conditioner R-273 Nick Fenton Repair completed on Service S802 - 08/06/2022 by Nick Fenton	
08/06/2022		A - 8 Wks S-802 Nick Fenton Had wheel alignment Flipper POS1 on rim Replaced batteries u/s Repaired A/C lines and gassed	
06/06/2022		Suspension - URGENT R-314 Nick Fenton	
31/05/2022		Other R-299 Nick Fenton	
30/05/2022		A - 8 Wks S-767 ATL Diesel Services - Jordan Hasenkam Exhaust leak - fitted new flex pipe Passenger seat missing - fitted Coolant leak from Header Tank - parts ordered	
17/05/2022		Brake Test Annual I-290 Gregory Fing PASS	
23/04/2022	405,245 kms 7,891 hrs	B - 35000 S-646 Hugh Middleton VDPH Maintenance Coordinator	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Air Filters Changed Header tank level switch broken - replaced slight wear RHF lower cab mount - stable bolt missing LHF grill - new bolt water ingress LH cab door - reposition cat cable LH & RH headlamp wiring insecure - secured wiring at rear required securing - secured air loss in cab at dash - secured fitting 5th wheel foot pad worn - new pads and bolts	
17/04/2022		Other R-208	Hugh Middleton VDPH Maintenance Coordinator
15/04/2022		Engine R-204	Hugh Middleton VDPH Maintenance Coordinator
03/04/2022		Chassis R-185	Hugh Middleton VDPH Maintenance Coordinator
03/04/2022		Wheels/Tyres - URGENT R-183	Hugh Middleton VDPH Maintenance Coordinator
01/04/2022		Fire Extinguisher Inspection I-229 LAST SERVICE APRIL 2022 - as per inspection sheet S-935 ON 26/07/2022	Internal Workshop
26/03/2022	388,074 kms	A - 8 Wks S-506 Front Engine Mount - weld crack	Hugh Middleton VDPH Maintenance Coordinator
20/03/2022		Cab R-170	Hugh Middleton VDPH Maintenance Coordinator
14/03/2022		Other R-161	Hugh Middleton VDPH Maintenance Coordinator
26/02/2022	370,284 kms	Lights - IMPORTANT R-128 Fit with new bulbs	Hugh Middleton VDPH Maintenance Coordinator
01/02/2022		Brake Test MNM 3 Monthly I-100 PASS	Nick Fenton
01/02/2022	368,689 kms	Brake Test Annual I-292 PASS	Nick Fenton
01/02/2022	368,689 kms	Brake Test Annual I-255	Nick Fenton
13/01/2022	368,035 kms 7,060 hrs	C - 100000 S-260 Ad Blu Filter & Air Filter & All driver tyres replaced Driver windscreen cracked, G/Change Floor Gator torn - Replaced, LH Fan Motor Panel Removed - Replaced, RH Tre Excessive wear - Replaced, Hood grill surround insecure - Replaced, RH Outer roof light inop - Replaced, Acc damage RH Stack cover + Pipe - S/able, Bonnet arch trim RH damage - Replaced, Bonnet decal missing - Replaced, LHR Tail lamp missing - Replaced, 3rd axle tie rod to diff bush u/s - Replaced, 2 & 3 Air tank belts broken - Replaced, Auto lube pipe burst RHF back & rear slack - adjusted, Fuel tank lap missing - Replaced, LH 2nd fuel tank cracked - Replaced, LH 3rd axle bump stop broken & RH 2nd - Replaced, Cat walk plate insecure - Secured, RH 2nd fuel tank strap insecure - Secured, LH 2nd air tank air pipe manifold U/S leaking - Replaced, Air pipe from relay valve to rear chaffed - Replaced	Hugh Middleton VDPH Maintenance Coordinator
31/12/2021		Fire Extinguisher Inspection I-200	Internal Workshop
07/12/2021	357,033 kms 6,826 hrs	A - 8 Wks S-421 Marker lights inop - Repair lights Vehicle very muddy need to be cleaned	SMS Group WA
24/11/2021		A - 8 Wks S-412 Prop centre bearing U/S - Replaced 2nd U/joint U/S - Replaced 1st input U/J not fitted securely - Replaced Adblue tank not venting - clear vents Extinguisher out of date - Serviced and restamped	Hugh Middleton VDPH Maintenance Coordinator
28/10/2021	343,733 kms	A - 8 Wks S-420	SMS Group WA

Date	Reading / Units	Type / Repairer Notes	Repairer
07/09/2021	313,667 kms	A - 8 Wks S-75 A Truck Service - Completed	Internal Workshop
21/05/2021	185,842 kms	B - 25000 S-154 B Truck Service - Completed	Internal Workshop
12/02/2021	133,248 kms 3,142 hrs	C - 100000 S-171 C TRUCK SERVICE - Completed	Internal Workshop
16/03/2020	42,646 kms	Brake Test Annual I-50 BRAKE TEST- Completed	

Signed: _____

Name: _____

Date: _____