



Vehicle History Summary



Fleet #	VD87
Registration	XQ07VE
Make	Kenworth
Model	K200
VIN / Chassis #	6F5000000BA444161
Build Date	2011

Date	Reading / Units	Type / Repairer Notes	Repairer
		COMPRESSOR, Leak - IMPORTANT R-12992	
		Cab, Electrical - IMPORTANT, Fault R-12835	
		Cab R-11975	
		WINDSCREEN WASHER / WIPER - IMPORTANT R-12498	
		Fault T-1509	
		Driveline, Fault R-12934	
		Exhaust R-12485	
		A - 14000 S-8971	
		Fuel R-12443	
		Cab, Engine R-12398	
		Fault, WINDOW - IMPORTANT R-13037	
14/05/2026		NHVAS R-11493	
27/02/2026	168,244 kms 14,285 hrs	COMPRESSOR R-12367 Inspection Compressor leaking oil from gasket between timing housing - order new one Engine oil filter neck need new hose between sump and pipe - order hose Needs new engine mounts at front - order Rear cab munts need replacing - order	Brad Deguara
20/02/2026	163,791 kms 14,250 hrs	Cab R-11914 REPLACE FUEL TANK SENDER, TEST OPERATION ALL OK	
20/02/2026	163,791 kms 14,250 hrs	Engine R-12181 FAULT REPAIRED WITH TURBO REPLACEMENT	
20/02/2026	163,791 kms 14,250 hrs	Damage R-12028 REPLACED INTERCOOLER PIPE WORK MOUNTS AS REQUIRED REPAIR EXHAUST AND TEST ALL MONITOR CAB MOUNTS	
20/02/2026	163,790 kms 14,250 hrs	Reverse Alarm - IMPORTANT R-12027	

Date	Reading / Units	Type / Repairer Notes	Repairer
		REPAIR WIRING TO REVERSE ALARM, TEST OPERATION ALL OK	
20/02/2026	163,790 kms 14,250 hrs	Hub Bearing / Seal - Urgent R-12012	VDPH Sarina
		REPLACE HUB SEAL, WASH AND CLEAN ALL PARTS AND REASSEMBLE AS REQUIRE FIT WHEELS TENSION TO SPEC ADJUST BRAKES AND TEST DRIVE	
20/02/2026	163,790 kms 14,250 hrs	Engine R-11915	
		REPLACE TURBO AND VGT CONTROLLER AS REQUIRED CONNECT COMPUTER AND CALIBRATE REFILL COOLANT TEST DRIVE ALL OK	
20/02/2026	163,790 kms 14,250 hrs	B - 28000 S-8426	VDPH Sarina
		COMPLETE SERVICE AND CHECK OVER	
20/02/2026	163,790 kms 14,250 hrs	WINDSCREEN WASHER / WIPER - IMPORTANT R-11858	
		TESTED ALL OK	
20/02/2026	163,791 kms 14,250 hrs	Cab R-11830	
		REPLACE CAB LIFT PUMP AND FILL WITH OIL TEST OPERATION ALL OK	
20/02/2026	163,790 kms 14,250 hrs	Diff R-11559	
		REMOVE JACK SHAFT R-R NEW JACK SHAFT SEAL AND SPEEDI SLEEVE REFIR AND TESNSION BOLTS	
20/02/2026	163,791 kms 14,250 hrs	Engine R-11495	
		REPAIRED ON JOB CARD 12028	
20/02/2026	163,790 kms 14,250 hrs	Engine, Gauges R-11494	
		CLEAR ALL CODES AND TEST DRIVE NO FAULTS COMEING UP	
26/01/2026	157,726 kms 14,102 hrs	Windscreen/Mirrors - IMPORTANT R-11148	
		WINDSCREENS REPLACED BY CQ MACHINERY GLASS	
24/01/2026	157,090 kms 14,689 hrs	Engine R-11876	Huntter Cannell
		Both fuel tanks drained Plugs inspected, dirt and alloy shavings present Crossover these removed & blown out, suction & return lines disconnected & blown out Pick up in main fuel tank removed and cleaned both filters changed & fuel water separator bowl cleaned	
24/01/2026	157,090 kms 14,089 hrs	Fuel Tank R-12098	VDPH Sarina
		DRAIN FUEL TANKS AND FLUSH OUT, FLUSH FUEL LINES, REPLACE FUEL FILTERS REFILL WITH CLEAN FUEL, PRIME SYSTEM, RUN AND TEST TRUCK ALL OK, CLEAN UP WORK AREA	
24/01/2026	157,090 kms 14,089 hrs	Lights - IMPORTANT R-11857	Huntter Cannell
		Terminal wiring damaged at reverse switch on gearbox Both terminals replaced & test	
08/01/2026	154,978 kms 14,043 hrs	Electrical - IMPORTANT R-11678	Huntter Cannell
		Inspected LHS indicator N/W Inspected wiring of trailer plug Found crack internals of suzi coil Replaced part as required Light test on trailer - all operational.	
08/01/2026	154,978 kms 14,043 hrs	Fire Extinguisher R-10747	Huntter Cannell
		Bracket fitted to gantry Extinguisher tested & fitted	

Date	Reading / Units	Type / Repairer Notes	Repairer
26/11/2025	147,639 kms	Broken R-10973 Repairs done at earlier date	Robert Brackowski
26/11/2025	147,639 kms	Windscreen/Mirrors - IMPORTANT R-10752 Repairs done at earlier date	Robert Brackowski
19/11/2025	146,205 kms	Engine R-10751 Hunnter replaced engine oil pressure gauge Brad tested on Road test	Brad Deguara, Huntter Cannell
18/11/2025	146,205 kms	Transmission/Clutch - URGENT R-10748 Diagnosed and replaced trans temp sensor Replace crimp	Brad Deguara
18/11/2025	146,205 kms	Fuel, Leak - IMPORTANT R-11125 Replaced all 4 fuel lines that were leaking tightened fittings going into fuel pump	
17/11/2025		Driveline, Leak - IMPORTANT R-11062 Resealed both diff centres Resealed all 4 rear axle sealing flanges	Brad Deguara
15/11/2025	146,128 kms	Air Conditioner R-10739 A/C high pressure horton fan cut in / out Switch replaced & wiring for A/C cut in / out Rubbed through - repaired	Huntter Cannell
15/11/2025	146,188 kms	Engine R-10746 Engine light issue fixed on inspection - no fault found	Huntter Cannell
15/11/2025	146,188 kms	D - 112000 S-7753	Huntter Cannell
15/11/2025	146,188 kms	Lights - IMPORTANT R-10749 Reverse g-box sensor replace & wiring at tail lights repaired	Huntter Cannell
13/09/2025	126,452 kms 13,600 hrs	B - 28000 S-7151 CHECK OVER FIT 9KG FIRE EXT TO TRUCK	Huntter Cannell
13/09/2025	126,452 kms 13,600 hrs	Electrical - IMPORTANT R-10401 REPLACE TRAILER PLUG CHECK AC PARTS ORDERED CHECK SLACK ADJUSTERS REPLACE POS 6 AND ADJUST ALL BRAKES AS REQUIRED REPAIR CRUISE LEVER TIGHTEN AS REQUIRED REPLACE GLOVE BOX LATCH REPAIR WASHER JETS REPAIR WALKWAY BOLTS	Huntter Cannell
17/08/2025	106,382 kms 13,282 hrs	A - 14000 S-6384 REPAIR GAURDS AND MUD FLAPS ADJUST ALL BRAKES AND ROAD TEST REPAIR WATER TANK	VDPH Sarina
02/08/2025	1,137,104 kms 13,385 hrs	Planned Maintenance R-10040 Turntable changed Height valves adjust Full grease Exhaust tightened Walkway moved	Huntter Cannell
25/07/2025	109,675 kms	Opportune Maintenance, Suspension - URGENT R-9803 Removed and replaced Both rear Ride Height Valves Tested, all operational	Mitch Grima
19/07/2025	106,382 kms 13,282 hrs	Cab R-9178 INSPECT AND UNJAM AS REQUIRED	Internal Workshop
17/07/2025	106,382 kms 13,282 hrs	WINDSCREEN WASHER / WIPER - IMPORTANT R-9176 REPAIR WASHER HOSE AND TEST OPERATION ALL OK	Internal Workshop
17/07/2025	106,382 kms 13,282 hrs	Cab R-9156 REPAIR DIFF TEMP SENSOR WIRING AND 1 X SENSOR HOK UP LAPTOP AND CLEAR ENG FAULT AND TEST DRIVE	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
25/06/2025	13,150 hrs	Engine, Planned Maintenance R-9619 Removed exhaust manifold and turbo Removed snapped manifold bolts in head Fitted exhaust manifold with new gaskets and new bolts Fitted Turbo Filled coolant Diagnosed air cond (high pressure switch) Replaced high pressure switch Diagnosed horton fan issue with not engaging and switch back to front Replaced horton solenoid because it was dicky Rectify horton fan issue due to someone in past plumbing solenoid up wrong Gassed up air cond Fitted chrome fenders above wheels undercab Fixed broken wire going to alternator run a new horton fan air line old one u/s Adjusted steering wheel Topped up Hyd tank (40L - 68W) Replaced O-Rings on hose I pulled off turbo	Brad Deguara
07/05/2025	87,761 kms 12,934 hrs	Engine R-9101 Engine oil pressure: 190kpa low idle (27psi) 260kpa high idle (37psi) Engine light was caused by blocked fuel filter not low oil pressure.	Timothy McFadzen Contracting
07/05/2025	87,761 kms 12,934 hrs	PTO R-9102 Fitted new diverter valve Fitted new air control box Run new air line Test ok	Frank Hale - All Crane & Heavy Vehicle Repairs
07/05/2025	87,761 kms 12,934 hrs	B - 28000 S-5938 Change eng oil & filter, fuel filters, tighten diff filter and refill diff, grease, tyre pressures, replace wiper blades, air filter, straighten steering wheel.	Timothy McFadzen Contracting
29/04/2025		Air Conditioner R-9177 Test a/c - Low gas Leak at compressor shaft seal Possible leaking evaporator Need to - Replace evaporator while removed and tx valve is being replaced Flush lines Change receiver dryer Replace compressor Pressure test - regas	East Coast Auto Electrical & Air Conditioning
06/02/2025	559,038 kms	Electrical - IMPORTANT, Other R-1874	Rob Brackowski - Callcorr
16/01/2025		Windscreen/Mirrors - IMPORTANT R-1796	Mark Matchett
27/08/2024		Fire Suppression - IMPORTANT R-2058 Truck is getting refurbished, repair will be completed in the rebuild.MM	Internal Workshop
23/11/2023		Wheels/Tyres - URGENT R-3642 See attached jobcard Removed both front springs & hangers Press bushes in hangers, tightened & torqued u bolts Torqued all rear wheels nuts Fabricated brackets for gauteys Fabricated bracket to mount cab tilt pump	Mark McLauchlan
06/11/2023		Chassis R-3367 See attached job form Brought 10mm plate to workshop - measure & cut with Rob Drill holes for chassis & gantry Drilled & measure holes on plate to cover opening on roof - siliconed & tightened bolts secure	Mark McLauchlan
01/11/2023		Fuel R-3366 See attached job form Pumped out diesel on both fuel tanks Removed fuel hoses & covered Removed fuel tank straps & removed fuel tanks Began to remove both front left hand & right hand L Brackets Placed forklift to hold Began removing gantry bolts & removed gantry Drained hydraulic tank & removed Straped gantry all brackets on gantry	Mark McLauchlan
10/10/2023		Fuel R-3365 See attached job form Fitted fuel tank L bracket Fuel cross over bracket	Mark McLauchlan
20/09/2023		Engine R-3364 See attached Job Forms Pressed out front tail shaft, uni joints & fitted new unit joints Fitted new Gear box & selector housing Fitted x 4 shocks on rear Fitted horton fan hub, retapped bolt holes on block & torqued bolts Removed L/H/F cab tilt ram & hoses Resealed ram, cleaned & fitted Cleaned up faces on exhaust & fitted new flexi & new clamps tightened secure Removed cab tilt ram on L/H/F Removed & replaced cab shoch tilt ram Fitted horton fan hub & fan	Mark McLauchlan
11/09/2023		Leak - IMPORTANT, Other, Transmission/Clutch - URGENT R-3933 See attached jobcard	Mark McLauchlan
04/07/2023		WINDSCREEN WASHER / WIPER - IMPORTANT R-1776 As per repair report - Replaced complete stalk	Rob Brackowski - Callcorr
04/07/2023	55,903 kms	B - 35000 S-2059	Rob Brackowski - Callcorr

Date	Reading / Units	Type / Repairer Notes	Repairer
		As per service report Exhaust flex after turbo about to crack Exhaust tip loose - replaced clamp Walk plate loose - made bracket and tightened Left & right front J brackets cracking RH front leaf sping has on leaf broken Selector housing side to side shift pin worn exessively Wiring rubbing on V bolts/front axle - P Clamped & cable tied up Radiator rubber mounts worn Side lights for tanks rough wiring EGR Pipe leaking at manifold - Tried to remove feels like x threading Cab tilt u/s - Replaced unit # plate light N/W - repaired wiring Clutch won't adjust & fork worn through bushes	
01/06/2023	44,198 kms 12,120 hrs	Other R-1686	DBE Heavy Vehicle Repairs
		Remove and pull apart horn - Found failed internally Remove heater hose from back of head to bottom of cab Fit new horton and flush coolant and replace with 60Litres red coolant	
17/02/2023	11,964 kms 11,557 hrs	B - 35000 S-1731	ATL Diesel Services - Jordan Hasenkam

Signed: _____

Name: _____

Date: _____