PLANT MAINTENANCE REPORT

Plant Description	SMU Date	SMU Hrs	Frame Hrs
16H#1 - GD001 - Caterpillar 16H Grader - S/N: ATS688	07/09/25	29,404	29,404

Comments

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Air Conditioner - -		Checked	working fine	0	11/06/25	
Cylinder - Centre Shift - -		Overhauled		0	29/05/24	29,399
Brake - Service - -		Repaired	replaced RHS rear service brake pipe leaking (rear of tandem)	0	27/03/24	29,399
Box - Battery - -		Cleaned		0	21/03/24	
Lights - -		Checked	all working	0	05/03/24	
- -		Checked		0	05/03/24	
Filter - Air Conditioning - -		Replaced		0	22/02/24	
Sensor - Air Filter Restriction - -		Replaced		0	21/02/24	
Fire System - -		Serviced	6 Monthly Fire Suppression Service	0	04/07/23	
Grease System - -		Repaired	Grease leak on steering repaired.	0	11/05/23	
Tyre - 4 -	F7N382212	Fitted		0	05/05/23	29,340
Alternator - -		Replaced		0	29/04/23	
Batteries - -		Replaced		0	29/04/23	
Fire System - -		Repaired	Pirtek topped up fire suppression system and reset controller	0	29/04/23	
500HR - -		Serviced	as per service sheet	0	30/03/23	29,319
Tyre - 1 -	F2E283555	Inspected		0	27/08/21	29,306
Tyre - 2 -	F2E283551	Inspected		0	27/08/21	29,306
Tyre - 3 -	F7S583642	Inspected		0	27/08/21	29,306

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Tyre - 4 -	0112NJI938	Inspected		0	27/08/21	29,306
Tyre - 5 -	F7S583644	Inspected		0	27/08/21	29,306
Tyre - 6 -	F7S482159	Inspected		0	27/08/21	29,306
Circle Box - -		Overhauled	fit new bushes, bearings and seals	0	15/08/21	29,246
250HR - -		Serviced	250HR Service as per service sheet	0	14/08/21	29,246
Tyre - 4 -	0112NJI938	Fitted		0	09/08/21	29,210
Brake - Park - -		Repaired	clean up wiring and replace relay for park brake	0	04/08/21	
Fire System - -		Serviced	Mandatory 6 monthly Fire Suppression Service	0	01/08/21	
Filter - Air Outer - -		Replaced		0	28/07/21	
Sensor - Brake Overstroke - -		Cleaned		0	14/07/21	
Fire System - -		Repaired		0	13/07/21	
Rim - 1 -	MME116	Fitted		0	06/07/21	29,041
Rim - 4 -	MME193	Fitted		0	06/07/21	29,041
Tyre - 1 -	F2E283555	Fitted		0	06/07/21	29,041
Tyre - 4 -	0112NJI909	Fitted		0	06/07/21	29,041
Breather - Fuel Tank - -		Replaced		0	30/06/21	
1000HR - -		Serviced	1000hr Service - Service as per service sheet	0	27/06/21	28,982
Fire System - -		Repaired		0	27/06/21	
Radio - Two Way - -		Tested	Tested during service and found operational.	0	26/06/21	
Sensor - Oil Pressure - -		Replaced		0	22/06/21	
Light - Flashing - -		Replaced	Replace blue strobe light on roof	0	18/06/21	
Cutting Edges - -		Replaced		0	03/06/21	
Pin - Blade Tilt Cylinder - -		Replaced		0	31/05/21	
Cylinder - Side Shift - -		Overhauled		0	17/05/21	28,748

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
250HR - -		Serviced	Service as per service sheet.	0	17/05/21	28,749
Radio - Two Way - -		Fitted	Fit External speaker radio.	0	13/05/21	
Cutting Edges - -		Replaced		0	11/05/21	
Engine - -		Repaired	replaced turbocharger	0	07/05/21	28,692
Turbocharger - -		Replaced		0	07/05/21	28,692
Rim - 1 -	MME275	Fitted		0	28/04/21	28,637
Tyre - 1 -	F7N382213	Fitted		0	28/04/21	28,637
Light - Flashing - -		Repaired	Repaired wiring on blue strobe light	0	27/04/21	
Electrical - -		Inspected		0	13/04/21	
Hose - Brake - -		Replaced		0	13/04/21	
Blade - -		Inspected	Repaired oil leak from under blade cushion accumulators	0	13/04/21	
500HR - -		Serviced		0	10/04/21	28,518
Hose - Hydraulic - -		Replaced	replace 2 hoses under LHS under cab	0	09/04/21	
Aerial - Two Way - -		Repaired	Clean up earth and tighten aerial.	0	05/04/21	
Hose - Hydraulic - -		Repaired	Repaired oil leak from valve supply hose under cab	0	28/03/21	
Rim - 4 -	MME272	Fitted		0	26/03/21	28,403
Tyre - 4 -	F7N382211	Fitted		0	26/03/21	28,403
Exhaust - -		Repaired	replaced exhaust pipe	0	23/03/21	
Cutting Edges - -		Replaced		0	16/03/21	
Belt - A/C - -		Replaced		0	05/03/21	
Machine - -		Inspected	Install ID number and run through checklist to make site ready.	0	04/03/21	28,266
Electrical - -		Inspected	6 monthly low voltage inspection	0	04/03/21	28,267
Brakes - -		Tested	6 month brake test	0	04/03/21	

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Fire System - -		Repaired		0	04/03/21	
Air System - -		Repaired	replaced air dryer assembly and air governor	0	25/01/21	28,266
Dryer - Air - -		Replaced	replaced whole assembly	0	25/01/21	28,266
Governor - Air Pressure - -		Replaced		0	25/01/21	28,266
250HR - -		Serviced		0	25/01/21	28,266
Tyre - 3 -		Repaired	Fitted L ring to pos 3 tyre inflate and fit back to machine	0	26/08/20	
Tyre - 2 -	F2E283551	Fitted		0	21/08/20	28,105
Steering - - Right		Repaired	replaced tie rod end	0	02/08/20	
2000HR - -		Serviced	service	0	25/07/20	28,031
Fire System - -		Recharged	discharged by accident	0	27/05/20	
Turbo Timer - -		Repaired	rearranged wiring for turbo timer, tested ok	0	18/05/20	
Grease System - -		Repaired	Replaced grease line	0	17/04/20	
Fire System - -		Fitted	New fire suppression system fitted	0	11/04/20	
Hose - Hydraulic Fan Motor - -		Replaced		0	01/04/20	
Machine - -		Paint	replace decals	0	31/03/20	0
Radiator - -		Repaired	remove radiator, remove cores and clean fit new rubbers to cores and refit back to radiator, clean top and bttom radiator tanks, refit radiator back to machine and test	0	31/03/20	0
Sight Glass - Hydraulic - -		Replaced	replace	0	13/03/20	
Blade - -		Repaired	replaced skin	0	16/12/19	0
Air Conditioner - -		Overhauled		0	25/10/19	27,865
Circle Group - -		Adjusted	new wear strips fitted	0	25/10/19	27,865
Cylinder - Blade Lift - - Left		Overhauled		0	25/10/19	27,865
Cylinder - Blade Lift - - Right		Overhauled		0	25/10/19	27,865

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Cylinder - Side Shift - -		Overhauled		0	25/10/19	27,865
Cylinder - Steering - - Left		Overhauled	replaced pins and bushes	0	25/10/19	27,865
Cylinder - Steering - - Right		Overhauled	replaced cylinder rod, pins and bushes	0	25/10/19	27,865
End - Tie Rod - - Left		Replaced	on steering linkage	0	25/10/19	27,865
End - Tie Rod - - Right		Replaced	on steering linkage	0	25/10/19	27,865
Hose - Transmission Cooler - -		Replaced		0	25/10/19	27,865
Mat - Floor - -		Replaced		0	25/10/19	27,865
Seal - Duo Cone - Rear - Right		Replaced		0	25/10/19	27,865
Tandem Drive - - Left		Repaired	resealed - fit new shims, fit new bushes to pivot	0	25/10/19	27,865
Turbo Timer - -		Replaced		0	25/10/19	27,865
250HR - -		Serviced		0	02/08/19	27,865
Hose - Hydraulic Suction - -		Repaired	tighten hoses	0	07/06/19	0
Radio - AM/FM - -		Replaced		0	03/05/19	0
Cutting Edges - -		Replaced		0	03/05/19	0
Grease System - -		Repaired	Repair grease fault	0	03/05/19	0
Hose - Coolant - -		Replaced		0	03/05/19	0
Pins - -		Inspected	Ultrasonic Pin Inspection	0	26/04/19	0
Valve - Control - -		Repaired	replaced plug on valve	0	22/03/19	0
Valve - Control - - Right		Repaired	Resealed rhs valve bank and replaced control lever shaft housing	0	04/03/19	0
Tyre - 4 -	0112NJI909	Fitted		0	15/01/19	27,480
Valve - Control - - Left		Resealed	Resealed valve bank on lhs valve and linkage group	0	05/01/19	27,460
500HR - -		Serviced		0	03/01/19	27,458
Cutting Edges - -		Replaced		0	18/12/18	27,410

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Boot - Ripper - -		Replaced		0	18/12/18	27,410
Lights - -		Repaired	refit headlights	0	05/12/18	27,364
Tyre - 2 -	0112NJ1915	Fitted		0	02/12/18	27,351
Pad - Blade Wear - -		Replaced		0	18/11/18	2,788
Windscreen Wiper System - -		Repaired	replaced rhs lower wiper blade	0	18/11/18	27,288
Pins - -		Replaced	replaced pins on moldboard	0	18/11/18	27,288
250HR - -		Serviced		0	18/11/18	27,288
Cutting Edges - -		Replaced		0	09/11/18	27,169
Latch - Door - -		Replaced		0	09/11/18	27,169
Cutting Edges - -		Replaced		0	07/11/18	27,136
Transmission - -		Repaired	replaced transmission shift cables	0	31/10/18	27,050
Blade - -		Repaired	linebore replace bushes and pins, replace sideshift wear pads	0	26/10/18	27,038
Circle Group - -		Repaired	Replaced top and bottom wear pads on circles	0	26/10/18	27,038
Solenoid - Start - -		Repaired	repaired wiring to start solenoid	0	26/10/18	27,038
Hose - Hydraulic - -		Replaced	replaced hose from pump	0	26/10/18	27,038
Sensor - Engine Oil Pressure - -		Replaced		0	16/10/18	27,024
1000HR - -		Serviced		0	14/10/18	27,017
Belt - A/C - -		Replaced		0	01/10/18	26,828
Belt - Alternator - -		Replaced		0	01/10/18	26,828
Tensioner - Belt - -		Replaced		0	01/10/18	26,828
Tine - Ripper - -		Fitted		0	25/09/18	26,772
250HR - -		Serviced		0	25/09/18	26,772
Lights - -		Replaced	Install new cab lights	0	23/09/18	0

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Cutting Edges - -		Replaced		0	21/09/18	26,721
Grease System - -		Inspected	Inspected - ok	0	19/09/18	
Light - Interior - -		Repaired	Repair wiring and replace bulb	0	07/09/18	26,544
Engine - -		Repaired	replaced idler pulley bearings	0	04/09/18	26,534
Pipe - Brake - Rear - Left		Replaced		0	04/09/18	26,534
Pump - Transmission - -		Replaced		0	04/09/18	26,534
Transmission - -		Overhauled		0	04/09/18	26,534
Fire System - -		Inspected	Fire Suppression Inspection - 6 monthly	0	02/09/18	0
Tyre - 1 -	F8B183488	Fitted		0	20/07/18	26,531
500HR - -		Serviced		0	16/07/18	26,508
Cutting Edges - -		Replaced		0	16/07/18	26,507
Mirror - - Right		Replaced		0	15/07/18	26,497
Tyre - 1 -		Repaired	replace O-ring	0	15/07/18	26,497
Air Conditioner - -		Repaired	Replace condensor fan fuse and relay	0	10/07/18	26,450
Cutting Edges - -		Replaced		0	07/07/18	26,419
Windscreen Wiper System - -		Replaced	replace wiper bottom front right	0	03/07/18	26,357
Meter - Hour - -		Repaired	Repair wiring to hour meter	0	03/07/18	26,357
Exhaust - -		Repaired	repair exhaust leak at turbo	0	03/07/18	26,357
Cutting Edges - -		Repaired	Replace broken cutting edge bolts	0	02/07/18	26,350
Radio - AM/FM - -		Repaired	replace aerial	0	29/06/18	26,311
Door - Engine Bay - -		Replaced		0	26/06/18	26,297
Rim - 1 -	MME116	Fitted		0	25/06/18	26,286
Rim - 2 -	MME073	Fitted		0	25/06/18	26,286
Tyre - 1 -	0312JCK93	Fitted		0	25/06/18	26,286

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Tyre - 2 -	0312JCS94	Fitted		0	25/06/18	26,286
Electrical - -		Repaired	wiring repaired in throttle lock	0	24/06/18	0
250HR - -		Serviced		0	23/06/18	26,286
Fuel System - -		Repaired	adapt up fuel wiggins	0	20/06/18	26,233
Electrical - -		Inspected	6 monthly low voltage inspection	0	14/06/18	26,167
Batteries - -		Replaced		0	13/06/18	26,138
Radio - Two Way - -		Repaired		0	13/06/18	26,138
Cab - -		Repaired		0	12/06/18	26,128
Cutting Edges - -		Replaced		0	12/06/18	26,128
2000HR - -		Serviced		0	01/06/18	26,010
Brakes - -		Tested	Mandatory 6 monthly	0	25/05/18	25,936
Grease System - -		Repaired	new grease harness fitted	0	22/05/18	0
Articulation - -		Repaired	overhauled cylinders, replace pins and bushes	0	22/05/18	25,929
Cylinder - Articulation - - Left		Overhauled	replaced pins	0	22/05/18	25,929
Cylinder - Articulation - - Right		Overhauled	replaced pins	0	22/05/18	25,929
Steering - -		Repaired	replaced	0	22/05/18	25,929
Pins - -		Tested	Ultrasonic Pin Inspection	0	20/05/18	0
Final Drive - - Left		Overhauled		0	15/05/18	25,930
Tandem Drive - - Left		Overhauled	rebuild oscillating hub	0	15/05/18	25,930
Boot - Ripper - -		Replaced		0	26/04/18	25,855
Cutting Edges - -		Replaced		0	26/04/18	25,855
Grease System - -		Repaired	Weld broken grease pot bracket	0	22/04/18	25,796
250HR - -		Serviced		0	19/04/18	25,776
Filter - Air Conditioning - -		Replaced		0	09/04/18	0

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Bolt - Cutting Edge - -		Replaced	Replace cutting edge bolts - Fit longer bolts	0	04/04/18	0
Handpiece - Two Way - -		Replaced		0	02/04/18	0
Light - Work - -		Repaired	Repair rear lights	0	29/03/18	0
Pipe - Coolant - -		Repaired	Removed pipe and braze up, refit all, fill coolant and test - all okay	0	29/03/18	0
Cutting Edges - -		Replaced		0	27/03/18	0
Grease line - -		Repaired		0	27/03/18	0
500HR - -		Serviced		0	25/03/18	25,503
Grease System - -		Repaired	Repair grease line	0	25/03/18	25,502
Grease Pot - -		Replaced		0	23/03/18	25,502
Fire System - -		Inspected	Fire Suppression Inspection - 6 monthly	0	17/03/18	0
Cylinder - Steering - - Left		Overhauled		0	15/03/18	25,373
Blade - -		Repaired	Gouge off worn blade skin, fit new section, fully weld	0	15/03/18	25,372
Clutch - -		Inspected		0	09/03/18	25,353
250HR - -		Serviced		0	02/03/18	25,297
Radiator - -		Cleaned		0	01/03/18	25,256
Cutting Edges - -		Replaced		0	28/02/18	25,244
Grease System - -		Repaired	Repair grease line	0	26/02/18	25,217
Air Conditioner - -		Repaired	replace fuse for a/c	0	23/02/18	25,197
Door - Engine Bay - -		Adjusted		0	23/02/18	25,197
Cutting Edges - -		Replaced		0	09/02/18	25,095
Switch - Air Pressure - -		Replaced	tighten loose earth	0	02/02/18	25,053
Blower - A/C - -		Repaired	repair wiring for A/C blower motor	0	02/02/18	25,053
Hose - Fuel - -		Replaced		0	29/01/18	25,045

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Blower - A/C - -		Repaired	replace fuse for blower fans	0	20/01/18	25,012
Circuit Breaker - -		Reset		0	17/01/18	24,987
1000HR - -		Serviced		0	14/01/18	24,987
Air Conditioner - -		Repaired	Replace a/c thermostat	0	11/01/18	24,978
Air Conditioner - -		Repaired	Repair wiring to relay, replace LH condensor fan	0	02/01/18	24,951
Valve - Control - - Right		Resealed	resealed valve bank on rhs valve and linkage group	0	11/12/17	0
Injector - Fuel - 4 -		Replaced	replaced no.4 fuel injector	0	08/12/17	24,857
Cutting Edges - -		Replaced		0	15/11/17	24,751
250HR - -		Serviced		0	11/11/17	24,740
Fuel System - -		Inspected	Carried out fuel injector cut out test and fuel solenoid test, removed all tappet covers and inspected injector contacts	0	10/11/17	24,736
Fire System - -		Inspected	6 monthly inspection	0	29/10/17	0
Steering - -		Repaired	Fit new tie rod end to lhs steering cylinder	0	26/10/17	24,652
Light - Reverse - -		Inspected	Inspected - couldn't fault	0	20/10/17	24,588
Pin - Tilt Cylinder - -		Repaired	Re-align cylinder and fit pin, weld bolt to pin	0	19/10/17	24,569
Pins - -		Inspected	Ultrasonic Pin Inspection	0	18/10/17	0
Slides - Blade - -		Replaced		0	17/10/17	24,562
Seat - -		Repaired	Adjusted air regulator	0	17/10/17	24,562
500HR - -		Serviced		0	12/10/17	24,526
Cutting Edges - -		Replaced		0	10/10/17	24,484
Seat - -		Inspected	Inspected - couldn’t fault	0	06/10/17	24,457
Cab - -		Repaired	Replace rubber boot on controls in cab,	0	01/10/17	24,423
Turbocharger - -		Replaced		0	01/10/17	24,423
Filter - Air Outer - -		Replaced		0	22/09/17	24,401

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Hose - Blade Lift - -		Replaced		0	21/09/17	24,385
Electrical - -		Checked	Checked wiring and plugs into the cab and ecm - all ok	0	19/09/17	24,358
250HR - -		Serviced		0	19/08/17	24,254
Articulation - -		Replaced	Replaced three broken inner bolts and rechecked the preload	0	25/07/17	24,104
Sensor - Coolant Temperature - -		Replaced		0	21/07/17	24,088
Cutting Edges - -		Replaced		0	21/07/17	24,088
4000HR - -		Serviced		0	13/07/17	24,019
Filter - Air Outer - -		Replaced		0	13/07/17	24,019
Seat - -		Inspected	Inspected - all ok	0	20/06/17	23,845
Door - -		Repaired	adjust and modify striker and latch	0	14/06/17	23,831
Cutting Edges - -		Replaced		0	27/05/17	23,761
Hose - Steering Cylinder - -		Replaced		0	27/05/17	23,761
Grease System - -		Repaired	replace loose fuse in controller	0	23/05/17	23,749
250HR - -		Serviced		0	22/05/17	23,751
Seat Belt - -		Replaced		0	19/05/17	23,743
Fuel System - -		Repaired	replaced quick fill	0	11/05/17	23,685
Filter - Air Outer - -		Replaced		0	05/05/17	23,639
Tandem Drive - -		Repaired	Fit new plug, check oil level and send to work	0	01/05/17	23,591
Cutting Edges - -		Replaced		0	29/04/17	23,570
Valve - Treadle - -		Replaced	Replaced treddle valve and o-rings on LH pilot valve main delivery fitting	0	27/04/17	53,238
Door - Engine Bay - -		Repaired	Repaired engine bay door latch	0	25/04/17	23,508
500HR - -		Serviced		0	22/04/17	23,492
Tyre - 3 -	F7S583642	Fitted		0	22/04/17	23,492

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Tyre - 4 -	F7S482158	Fitted		0	22/04/17	23,492
Tyre - 5 -	F7S583644	Fitted		0	22/04/17	23,492
Tyre - 6 -	F7S482159	Fitted		0	22/04/17	23,492
Electrical - -		Repaired	repaired fault	0	21/04/17	23,489
Tyre - 6 -		Fitted		0	18/04/17	23,465
Compressor - A/C - -		Repaired	Repaired bad connection on pressure switch at the rear of compressor	0	15/04/17	23,457
Air System - -		Repaired	fit new air lines to lhs	0	07/04/17	23,388
Batteries - -		Replaced		0	07/04/17	23,388
Fuel Tank - -		Replaced		0	07/04/17	23,388
Hose - Hydraulic Fan Return - -		Replaced		0	07/04/17	23,388
Hose - Park Brake - -		Replaced	Replace prake brake release hose,	0	07/04/17	23,388
Hose - Ripper Lift Cylinder - -		Replaced		0	07/04/17	23,388
Hose - Transmission Cooler - -		Replaced		0	07/04/17	23,388
Motor - Starter - -		Replaced		0	07/04/17	23,388
Solenoid - Diff Lock - -		Replaced		0	07/04/17	23,388
Seat - -		Replaced		0	14/02/17	23,363
Lights - -		Repaired	C/O front LH high beam light and repair wiring on low beam	0	13/02/17	23,362
Lights - -		Adjusted	Tighten loose light bracket on front of gooseneck	0	12/02/17	23,362
Valve - Transmission Relief - -		Resealed		0	10/02/17	23,363
Radiator - -		Cleaned	washed out radiator	0	27/01/17	23,318
Cooling System - -		Repaired	Replace coolant bleed valve on top of motor	0	27/01/17	23,318
Cutting Edges - -		Repaired	Replaced RH and LH underlays	0	20/01/17	23,291
250HR - -		Serviced		0	18/01/17	23,275

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Air Conditioner - -		Repaired	Clean out evaporator, repair electrical fault	0	16/01/17	23,248
Cutting Edges - -		Replaced		0	12/01/17	23,236
Air Conditioner - -		Repaired	Change out high side pressure switch	0	10/01/17	23,233
Cooling System - -		Repaired	Replace broken fitting on coolant bleed line	0	06/01/17	23,233
Batteries - -		Inspected	Check battery terminals and alt belt and connections - all ok, couldn't fault	0	13/12/16	23,132
Pins - -		Inspected	Ultrasonic pin inspection	0	20/11/16	23,044
Compressor - A/C - -		Repaired	repair wiring	0	16/11/16	23,044
Grease line - -		Repaired	Bleed grease lines	0	16/11/16	23,044
Door - Engine Bay - -		Repaired	repaired engine bay door latch	0	07/11/16	23,016
Brakes - -		Tested	6 monthly	0	01/11/16	22,991
Transmission - -		Resampled		0	24/10/16	22,991
Light - Interior - -		Inspected	inspected - no fault found	0	23/10/16	22,991
Seat - -		Repaired	fit new seat slides and adjust lever	0	18/10/16	22,991
Radio - AM/FM - -		Replaced	Replace am/fm radio and aerial	0	14/10/16	22,991
Cutting Edges - -		Replaced	change out broken cutting edges	0	14/10/16	22,991
1000HR - -		Serviced		0	07/10/16	22,982
Fuel System - -		Repaired	resealed lhs fuel tank sender	0	07/10/16	22,982
Cutting Edges - -		Replaced		0	12/08/16	22,910
Fire System - -		Serviced	yearly service - new nozzle caps installed	0	07/08/16	22,884
Light - Work - -		Adjusted		0	20/07/16	22,841
Hose - Fuel - -		Replaced	Replace blown RH tank vent hose	0	07/05/16	0
Pins - -		Inspected	no cracking detected	0	21/04/16	22,811
Brakes - -		Tested - Dynami	Dynamic brake test - 6 monthly	0	19/04/16	22,811

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Bolt - Cutting Edge - -		Repaired	tightened	0	05/04/16	22,789
Transmission - -		Repaired	Replaced top of gear shift lever	0	29/03/16	22,776
Hose - Air Compressor - -		Replaced		0	24/03/16	22,755
Hose - Air Conditioning - -		Replaced		0	24/03/16	22,755
Cylinder - Steering - - Left		Repaired	tightened tie rod end	0	24/03/16	22,755
250HR - -		Serviced		0	23/03/16	22,755
Radio - AM/FM - -		Repaired	Check out am/fm radio, wriggled wires picked up stations	0	16/03/16	22,725
Cooling System - -		Flushed	Flush cooling system and fill up	0	10/03/16	22,712
Sensor - Engine Oil Pressure - -		Repaired	Secure loose plug to engine oil pressure sensor with zip tie	0	07/03/16	22,698
Light - Work - - Left		Replaced		0	03/03/16	22,686
Air System - -		Repaired	Replaced air hose and duster in cab	0	03/03/16	22,686
Cutting Edges - -		Replaced		0	28/02/16	22,667
Grease System - -		Inspected	bleed up system	0	28/02/16	22,667
Fan - Condensor - -		Replaced		0	11/02/16	22,616
Oil - Transmission - -		Replaced	Resampled transmission oil and changed	0	03/02/16	22,560
Air Conditioner - -		Repaired	replaced a/c condensor fan	0	02/02/16	22,558
Engine - -	5ED04656	Repaired	Engine oil pressure fault - cleaned sensor no further issues	0	02/02/16	22,558
Circle Group - -		Adjusted		0	29/01/16	22,538
Cylinder - Blade Lift - -		Adjusted		0	29/01/16	22,538
Fire System - -		Repaired	replaced 2 broken nozzle caps and tighten discharge hose fitting	0	28/01/16	22,525
Fire System - -		Serviced	Level 1	0	28/01/16	22,525
Tank - Fuel - -		Repaired	Replaced rubber seals in tank for sender and plates	0	28/01/16	22,525
500HR - -		Serviced		0	25/01/16	22,511

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Column - Steering - -		Repaired	wont retract - freed up	0	19/01/16	22,432
Seat - -		Repaired	reattached spring to lever for slide	0	19/01/16	22,432
Alternator - -		Replaced		0	30/11/15	22,346
Pins - -		Inspected	no cracking detected	0	22/11/15	22,309
Seat - -		Repaired	Remove seat and refit cable to lever	0	13/11/15	22,295
Brakes - -		Tested - Dynami		0	28/10/15	22,268
Brakes - -		Repaired	replaced treadle valve	0	28/10/15	22,268
Valve - Treadle - -		Replaced		0	28/10/15	22,268
250HR - -		Serviced		0	19/10/15	22,252
Blade - -		Repaired	free up blade travel	0	17/10/15	22,232
Cutting Edges - -		Replaced		0	17/10/15	22,232
Gasket - Rocker Cover - -		Replaced		0	09/10/15	22,188
Injector - Fuel - 2 -		Replaced		0	09/10/15	22,188
Air Conditioner - -		Regassed		0	29/09/15	22,167
Filter - Air Conditioning - -		Replaced		0	29/09/15	22,167
Engine - -	5ED04656	Inspected	Connected ET to machine, load test injectors, check turbo waste gate operation ok could not fault	0	17/09/15	22,164
Engine - Valve Set - -	5ED04656	Valve Set		0	17/09/15	22,164
Air Conditioner - -		Serviced	Service air conditioner, replaced recevier drier, cleaned condensor	0	12/09/15	22,164
Condensor - -		Cleaned		0	12/09/15	22,164
Receiver Dryer - -		Replaced		0	12/09/15	22,164
Exhaust - -		Repaired	replaced rain flap	0	08/09/15	22,160
Radio - AM/FM - -		Replaced		0	27/08/15	22,135
Coolant - -		Replaced		0	18/08/15	22,121

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Oil - Differential - -		Replaced		0	18/08/15	22,121
Oil - Transmission - -		Replaced		0	18/08/15	22,121
Oil Cooler - Transmission - -		Replaced		0	18/08/15	22,121
Radiator - -		Flushed		0	18/08/15	22,121
Fire System - -	GD1FS1	Inspected	Level 5 inspection carried out, replaced out of date cartridges, replace 3 missing nozzle caps and replaced all o-rings, inspected fire extinguisher	0	14/08/15	22,120
Brakes - -		Tested - Dynami	6 monthly	0	21/07/15	22,107
Cylinder - Blade Lift - -		Repaired	replaced inserts and shims on lift cylinder	0	09/06/15	22,051
Column - Steering - -		Adjusted		0	25/05/15	22,015
Engine - Valve Set - -		Valve Set		0	23/05/15	22,011
2000HR - -		Serviced		0	21/05/15	22,005
Filter - Fuel - -		Replaced		0	21/05/15	21,998
Fuel System - -		Cleaned	blow back along lines to fuel tank	0	21/05/15	21,998
Injector - Fuel - -		Tested	load tested all good	0	21/05/15	21,998
Grease System - -		Repaired	Bleed grease system	0	27/04/15	21,936
Slides - Blade - -		Replaced		0	22/04/15	21,933
Pins - -		Inspected	Ultrasonic pin inspection	0	13/04/15	21,910
Cutting Edges - -		Replaced		0	04/04/15	21,894
Light - Flashing - -		Replaced		0	08/03/15	21,857
Fan - Condensor - -		Repaired	Repair open circuit in wiring for condensor fan	0	27/02/15	21,838
Hose - Steering Cylinder - - Left		Replaced		0	09/02/15	21,780
250HR - -		Serviced		0	30/01/15	21,743
Fire Extinguisher - -		Inspected		0	19/01/15	21,725

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Fire System - -	GD1FS1	Inspected	level 2	0	19/01/15	21,725
Column - Steering - -		Checked	tighten loose steering column	0	12/01/15	21,697
Line - Grease - -		Replaced	Replaced broken grease line to front pivot pin	0	07/01/15	21,689
Pads - Circle Wear - -		Replaced		0	07/01/15	21,689
Circle Group - -		Adjusted	Replaced circle group slides and adjust	0	15/12/14	21,670
Slide - Circle Group - -		Replaced		0	15/12/14	21,670
Lights - Dash - -		Repaired	Replaced instrument panel bulbs	0	25/11/14	21,599
Slides - Blade - Lower -		Replaced	Replace lower blade slides and shim	0	04/11/14	21,591
Tyre - 1 -	FOM381200	Fitted		0	24/10/14	21,549
Tyre - 2 -	FOM381474	Fitted		0	24/10/14	21,549
Tyre - 3 -	0112NJI938	Fitted		0	24/10/14	21,549
Tyre - 4 -	0112NJI915	Fitted		0	24/10/14	21,549
Tyre - 5 -	0112NJI909	Fitted		0	24/10/14	21,549
Tyre - 6 -	0112NJI910	Fitted		0	24/10/14	21,549
Tyre - 1 -	FGF0560V0A	Fitted		0	21/10/14	21,527
500HR - -		Serviced		0	14/10/14	21,509
Light - Work - Rear - Right		Replaced	Replaced rhs rear work light	0	13/10/14	21,492
Pins - -		Inspected	Ultrasonic pin inspection No cracking detected	0	12/10/14	21,482
Cutting Edges - -		Replaced		0	10/10/14	21,467
Hose - Radiator - Bottom -		Replaced	Replaced bottom radiator hose	0	24/09/14	21,354
Brakes - -		Tested - Dynami	6 monthly	0	05/08/14	21,295
Tyre - 1 -	FJ09J0396	Fitted		0	15/07/14	21,252
Tyre - 2 -	FJ09J0251	Fitted		0	15/07/14	21,252
Arm - Wiper - Lower - Right		Replaced		0	14/07/14	21,252

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Mirror - - Right		Replaced		0	12/07/14	21,252
250HR - -		Serviced		0	12/07/14	21,252
Fire System - -	GD1FS1	Serviced	level 2	0	10/07/14	21,225
Motor - A/C Fan - -		Replaced		0	05/07/14	21,201
Cutting Edges - -		Replaced		0	04/07/14	21,193
Cutting Edges - -		Replaced		0	30/06/14	21,156
1000HR - -		Serviced		0	31/05/14	21,008
Mount - Cab - -		Replaced		0	15/05/14	20,963
Arm - Wiper - Front - Left		Replaced		0	06/05/14	20,944
E stop - -		Repaired	clean contact at E stop	0	18/04/14	20,856
Cutting Edges - -		Replaced		0	02/04/14	20,761
Column - Steering - -		Repaired	Repair column lock on steering column	0	30/03/14	20,758
Tyre - 1 -	K20CDD849	Fitted		0	28/03/14	20,743
250HR - -		Serviced		0	27/03/14	20,743
Cutting Edges - -		Replaced		0	19/03/14	20,721
End - Tie Rod - - Right		Replaced	Replaced rhs tie rod end on steering cylinder	0	23/01/14	20,506
500HR - -		Serviced		0	17/01/14	20,499
Fire System - -		Inspected	Level 1	0	15/01/14	20,489
Brakes - -		Tested	6 monthly	0	14/01/14	20,469
Grease System - -		Checked	Bleed system and reset - all works ok	0	13/01/14	20,454
Line - Grease - -		Replaced	Replace broken grease line and bleed out system	0	02/01/14	20,418
Hose - Engine Oil Filter Housing - -		Repaired	Reseal oil filter housing top hose	0	01/01/14	20,408
Slides - Blade - -		Repaired	Adjust and shim blade slides	0	28/12/13	20,390
Cutting Edges - -		Replaced		0	17/12/13	20,342

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Engine - -	5ED04656	Repaired	Hastings Deering resealed all injectors and replaced injector hold down bolts, carry out valve set and injector set, change engine oil and filter	0	14/12/13	20,325
Engine - Valve Set - -	5ED04656	Valve Set		0	14/12/13	20,325
Filter - Oil Engine - -		Replaced		0	14/12/13	20,325
Injector - Fuel - -		Resealed	All injectors resealed	0	14/12/13	20,325
Oil - Engine - -		Replaced		0	14/12/13	20,325
Light - Flashing - -		Replaced		0	07/12/13	20,301
Air Conditioner - -		Repaired	Install a/c cover on a/c compressor	0	07/12/13	20,301
250HR - -		Serviced		0	06/12/13	20,283
Brakes - -		Repaired	replaced brake lines	0	29/11/13	20,206
Switch - Park Brake Pressure - -		Replaced		0	23/11/13	20,154
Radio - AM/FM - -		Replaced		0	23/11/13	20,154
Engine - Valve Set - -	5ED04656	Valve Set		0	10/11/13	20,106
Radio - Two Way - -		Replaced		0	27/10/13	20,078
Batteries - -		Replaced	x2	0	16/10/13	20,020
Isolator - Battery - -		Replaced		0	16/10/13	20,020
4000HR - -		Serviced		0	10/10/13	19,993
Cylinder - Ripper Lift - -		Overhauled		0	04/10/13	19,963
Filter - Oil Engine - -		Replaced		0	28/09/13	19,901
Oil - Engine - -		Replaced		0	28/09/13	19,901
Cutting Edges - -		Replaced		0	28/09/13	19,901
Aftercooler - -		Replaced		0	25/09/13	19,865
Engine - -	5ED04656	Fitted		0	25/09/13	19,865

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Radiator - -		Overhauled		0	25/09/13	19,865
Light - Work - - Right		Fitted	x 2	0	24/09/13	19,865
Condensor - -		Replaced	Replace a/c condensor and fans vac system down	0	24/09/13	19,865
Fire System - -		Inspected	Level 2	0	30/07/13	19,854
Compressor - A/C - -		Replaced		0	26/07/13	19,854
Receiver Dryer - -		Replaced		0	26/07/13	19,854
Pins - -		Tested	Ultrasonic pin test	0	24/07/13	19,843
Brakes - -		Tested	6 monthly	0	23/07/13	19,844
Final Drive - Rear - Left		Overhauled		0	23/07/13	19,835
Final Drive - Rear - Right		Replaced		0	23/07/13	19,835
Light - Work - -		Replaced	Install new diff lights and wiring harness	0	23/07/13	19,835
Exhaust - -		Repaired	Free up clamps and tighten from turbo to muffler	0	21/07/13	19,834
Air Conditioner - -		Repaired	Repair heater switch	0	12/06/13	19,794
Sensor - Fuel Gauge - -		Replaced		0	04/06/13	19,784
Tie Rod Group - Steering Cylinder - - Left		Replaced		0	20/05/13	19,707
Hose - Radiator - -		Replaced	changed out all radiator hoses	0	18/05/13	19,707
Oil Cooler - Transmission - -		Replaced		0	18/05/13	19,707
Pads - Circle Wear - -		Replaced		0	18/05/13	19,707
Transmission - -	DWH01153	Rebuilt		0	18/05/13	19,707
Drive Group - Circle - -		Repaired	Circle wear pads replaced	0	16/05/13	19,707
250HR - -		Serviced		0	16/05/13	19,707
Hose - Control Valve - - Right		Replaced	replace hydraulic hose from pump to control valve	0	08/03/13	19,674
Steering - -		Repaired	replace stut in steering console	0	08/03/13	19,674

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Slides - Blade - -		Repaired	Remove blade slides, build up plates that hold slides in place	0	08/03/13	19,674
Grease System - -		Repaired	Repair broken terminal on switch, replace	0	08/03/13	19,674
Pump - Hydraulic - -		Replaced		0	04/03/13	19,658
Lights - -		Repaired	Repair wiring to front lights and replaced bulbs on rear worklight	0	21/02/13	19,568
Sensor - Coolant Temperature - -		Replaced		0	13/02/13	19,525
Cutting Edges - -		Replaced		0	01/02/13	19,509
Electrical - -		Repaired	checked diff lock switch - ok, checked sensor loose connection on connector - repaired	0	25/01/13	19,482
Slides - Blade - Top -		Replaced	x 2	0	17/01/13	19,481
500HR - -		Serviced		0	17/01/13	19,481
Lights - -		Repaired	Replace bulb in reverse light	0	09/01/13	19,439
Tyre - 2 -	S6B003266	Fitted		0	04/01/13	19,412
Hose - Air Conditioning - -		Replaced		0	06/12/12	19,296
Compressor - -		Replaced		0	05/12/12	19,296
Dryer - Air - -		Replaced		0	01/12/12	19,296
Dryer - Air - -		Rekit		0	26/11/12	19,258
250HR - -		Serviced		0	24/11/12	19,248
Air Conditioner - -		Repaired	Fix condenser fan and regas 1.2kg	0	19/11/12	19,192
Air System - -		Repaired	Rekit dryer - test ok - replaced air drier filter	0	08/11/12	19,110
Blade - -		Reskinned		0	05/11/12	19,091
Lights - -		Replaced	Install 4 x LED lights on cab and replace headlights	0	05/11/12	19,091
Lights - -		Repaired	Fix 3 x cab lights	0	01/11/12	19,080
Cylinder - Blade Tip - -		Overhauled		0	28/10/12	17,026

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Cylinder - Centre Shift - -		Overhauled		0	28/10/12	17,026
1000HR - -		Serviced		0	25/10/12	19,014
Air Conditioner - -		Repaired	Cleaned evaporator and replaced cab filter	0	21/10/12	18,987
Line - Air - -		Replaced		0	11/10/12	18,905
Brakes - Front - Left		Rebuilt		0	30/09/12	18,826
Brakes - Front - Right		Rebuilt		0	30/09/12	18,826
Brakes - Rear - Left		Rebuilt		0	30/09/12	18,826
Brakes - Rear - Right		Rebuilt		0	30/09/12	18,826
Chain - Drive - - Left		Replaced		0	30/09/12	18,826
Chain - Drive - - Right		Replaced		0	30/09/12	18,826
Tandem Drive - - Left		Rebuilt		0	30/09/12	18,826
Brakes - -		Tested	dynamic brake test after major brake work	0	30/09/12	18,826
Cooling System - -		Repaired	tightened clamps and topped up radiator - rechecked	0	19/09/12	18,783
Light - Flashing - -		Replaced		0	19/09/12	18,786
Pump - Water - -		Replaced		0	14/09/12	18,746
Boot - Ripper - -		Replaced		0	14/09/12	18,755
250HR - -		Serviced		0	13/09/12	18,746
Air Conditioner - -		Repaired	Mounted 2 condensor fans and modified wiring to suit	0	08/09/12	18,705
Lights - -		Repaired	Repair rear light switch	0	06/09/12	18,668
Cutting Edges - -		Replaced		0	04/09/12	18,657
Slides - Blade - -		Replaced		0	04/09/12	18,657
Air System - -		Repaired	Replaced air governor and pressure relief valve on compressor	0	29/08/12	18,605
Governor - Air Pressure - -		Replaced		0	29/08/12	18,605

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Lights - -		Repaired	Back lights moved above rippers to right hand side above rippers	0	28/08/12	18,594
Relay - Grease System - -		Replaced		0	26/08/12	18,584
Air System - -		Repaired	Changed air dryer filter and adjusted governor valve to 120psi	0	26/08/12	18,584
Compressor - -		Repaired	Replaced air compressor relief valve, adjust governor and check operation	0	22/08/12	18,556
Engine - -		Repaired	Repaired hose on waste gate rubbing on intake hose	0	20/08/12	18,535
500HR - -		Serviced		0	17/08/12	18,525
Isolator - Battery - -		Replaced		0	31/07/12	18,333
Air Drier - -		Repaired	Air dryer leaking - removed, resealed and reinstalled	0	23/07/12	18,253
250HR - -		Serviced		0	22/07/12	18,244
Light - Interior - -		Repaired	Repaired wiring	0	22/07/12	18,244
Batteries - -		Replaced			16/07/12	18,195
Cutting Edges - -		Replaced			16/07/12	18,195
Drive Group - Circle - -		Rebuilt		0	06/07/12	18,098
Motor - Wiper - -		Replaced		0	26/06/12	18,041
2000HR - -		Serviced		0	24/06/12	18,036
Air Conditioner - -		Repaired	replaced blown fuse for a/c blower fan	0	22/06/12	18,027
Spool - Valve Body - -		Replaced		0	10/06/12	17,868
250HR - -		Serviced		0	25/05/12	17,721
Valve - Control - - Left		Repaired	fitted new sandwich plate to lhs control valve and replaced blade lift valve	0	25/05/12	17,721
Light - Work - Rear -		Replaced		0	19/05/12	17,657
Lights - Head - - Left		Replaced		0	19/05/12	17,657
Lights - Head - - Right		Replaced		0	19/05/12	17,657

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Cutting Edges - -		Replaced		0	15/05/12	17,623
500HR - -		Serviced		0	02/05/12	17,510
Tyre - 2 -	D080506A03	Fitted		0	24/04/12	17,422
Lights - -		Replaced	Replace front and rear lights	0	22/04/12	17,411
Radio - AM/FM - -		Replaced		0	20/04/12	17,402
Cylinder - Wheel Lean - -		Overhauled		0	12/04/12	17,340
Radio - Two Way - -		Repaired	fixed aerial	0	09/04/12	17,308
Air Conditioner - -		Repacked	Fix wire on pressure switch	0	06/04/12	17,302
250HR - -		Serviced		0	31/03/12	17,249
Valve - Control - - Right		Repaired	Remove rhs control valve - replace broken plug and reseal hose and refit to machine	0	29/03/12	17,228
Belt - Alternator - -		Replaced		0	28/03/12	17,205
Valve - control - - Left		Resealed		0	17/03/12	17,129
Light - Interior - -		Repaired		0	11/03/12	0
Cutting Edges - -		Replaced		0	09/03/12	0
Valve - Control - - Right		Repaired	Fix leak at rhs control valve	0	09/03/12	0
1000HR - -		Serviced		0	27/02/12	16,966
Mat - Floor - -		Replaced		0	23/02/12	0
Air Conditioner - -		Repaired	Repair short and replace fuse for A/C blower	0	27/01/12	16,741
250HR - -		Serviced		0	25/01/12	16,731
Grease System - -		Repaired	Replace connection on grease pump	0	25/01/12	16,731
Electrical - -		Repaired	fix wiring connection on all lights, relay	0	25/01/12	16,731
Hose - Steering - -		Replaced		0	18/01/12	16,690
Tandem Drive - - Right		Rebuilt	Replace pivot housing and reassemble rhs tandem	0	17/01/12	16,684

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Circle Group - -		Repaired	Repair cracks, regroove circle recess and fit new segments	0	17/01/12	16,684
Draw Bar Group - -		Repaired	New ball joints fitted to drag link	0	17/01/12	16,684
A Frame - -		Repaired	repair crack in A frame	0	17/01/12	16,684
Cutting Edges - -		Replaced		0	17/01/12	16,684
Harness - Cab Console - -		Replaced		0	15/01/12	16,684
Harness - Engine - -		Replaced		0	15/01/12	16,684
Harness - Front - -		Replaced		0	15/01/12	16,684
Harness - Rear - -		Replaced		0	15/01/12	16,684
Harness - Steering Console - -		Replaced		0	15/01/12	16,684
Hydraulics - -		Repaired	Remove and clean out pilot signal relief valve	0	15/01/12	16,684
Valve - Control - - Left		Overhauled		0	30/12/11	16,684
Valve - Control - - Right		Overhauled		0	30/12/11	16,684
Pulley - Alternator - -		Replaced		0	30/12/11	16,684
Steering - -		Repaired	replaced tie rod ends	0	24/12/11	16,684
Pin - Cylinder Articulation - -		Replaced		0	24/12/11	16,684
Slides - Blade - -		Replaced	x 2	0	14/12/11	16,647
Wheel Bearing - -		Checked	Raise front and check wheel bearings - OK	0	04/12/11	16,569
500HR - -		Serviced		0	17/11/11	16,501
Receiver Dryer - -		Replaced		0	15/11/11	16,487
Electrical - -		Repaired	Checked trubo timer, wiring harness and neutral switch, change out relay	0	13/11/11	16,482
E stop - -		Repaired	repaired loose connection	0	02/11/11	16,415
Cutting Edges - -		Replaced		0	18/10/11	16,251
250HR - -		Serviced		0	16/10/11	16,246

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Windscreen Wiper System - -		Repaired	Change out wiper arm and blade	0	09/10/11	16,163
Rim - 1 -	MME077	Fitted		0	08/10/11	16,163
Rim - 2 -	MME075	Fitted		0	08/10/11	16,163
Tyre - 1 -	D081220C02	Fitted		0	08/10/11	16,163
Tyre - 2 -	D081222C02	Fitted		0	08/10/11	16,163
4000HR - -		Serviced		0	17/09/11	15,995
Motor - Wiper - -		Replaced		0	01/09/11	15,861
Rim - 3 -	MME192	Fitted		0	28/08/11	15,822
Rim - 4 -	MME193	Fitted		0	28/08/11	15,822
Rim - 5 -	MME191	Fitted		0	28/08/11	15,822
Rim - 6 -	MME194	Fitted		0	28/08/11	15,822
250HR - -		Serviced		0	17/08/11	15,770
Switch - Light - -		Replaced		0	02/08/11	15,655
Hose - Hydraulic - -		Replaced		0	26/07/11	15,591
500HR - -		Serviced		0	21/07/11	15,537
Switch - Light - -		Replaced		0	19/07/11	15,491
Cutting Edges - -		Replaced		0	05/07/11	15,386
Hose - Hydraulic - -		Replaced	to control valve	0	01/07/11	15,349
250HR - -		Serviced		0	23/06/11	15,271
Belt - Alternator - -		Replaced		0	15/06/11	15,168
Belt - Alternator - -		Replaced		0	08/06/11	15,115
Differential - -		Overhauled		0	07/06/11	15,111
Pump - Transmission - -		Overhauled		0	07/06/11	15,111
Solenoid - Diff Lock - -		Overhauled		0	07/06/11	15,111

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Transmission - -		Overhauled		0	07/06/11	15,111
Valve Body Assy - Transmission Relief - -		Overhauled		0	07/06/11	15,111
Valve Bank - -		Resealed		0	07/06/11	15,111
Hose - Radiator - Bottom -		Replaced		0	24/04/11	14,061
Pin - Steering - -		Replaced		0	24/04/11	15,020
Cutting Edges - -		Replaced		0	08/04/11	14,894
Tyre - -	FOM383397	Fitted		0	28/02/11	14,532
Tyre - 5 -	FOM381200	Fitted		0	28/02/11	14,532
Tyre - 6 -	FOM381474	Fitted		0	28/02/11	14,532
Accumulator - A/C - -		Replaced		0	16/12/10	13,850
Evaporator - A/C - -		Replaced		0	16/12/10	13,850
Receiver Dryer - -		Replaced		0	16/12/10	13,850
Thermostat - A/C - -		Replaced		0	16/12/10	13,850
Cutting Edges - -		Replaced		0	28/10/10	13,380
Seal - Blade Lift Cylinder Cap - -		Replaced		0	22/10/10	13,300
Slides - Blade - -		Replaced		0	22/10/10	13,300
Motor - Wiper - -		Replaced		0	22/10/10	13,360
Cutting Edges - -		Replaced		0	23/08/10	12,830
Tie Rod Group - Steering Cylinder - -		Replaced		0	25/07/10	1,596
Disc - Circle Drive - -		Replaced		0	05/05/10	11,883
Cutting Edges - -		Replaced		0	15/02/10	11,200
Booster - Park Brake - -		Replaced		0	22/12/09	10,985
Transmission - -		Replaced	reman from shed	0	15/08/09	9,600
Housing - Transmission Filter - -		Resealed		0	05/01/09	7,850

Component	Component ID	Action	Comments	Previous Hrs	Date Complete	Frame Hrs
Valve - Implement - - Left		Resealed		0	05/01/09	7,850
Valve - Implement - - Right		Resealed		0	05/01/09	7,850
Cutting Edges - -		Replaced		0	30/11/08	7,600
Bearing - Circle Drive - -		Replaced		0	28/08/08	6,561
Pinion Gear - Circle Drive - -		Replaced		0	28/08/08	6,561
Batteries - -		Replaced		0	09/08/08	6,401
Pump - Water - -		Replaced		0	16/06/08	5,739
Turbocharger - -		Replaced		0	15/06/08	5,739