RDO Equipment Pty Ltd
2 Chalcedony Road
Emerald QLD 4720
Ph 07 4843 8500
ABN: 58 060 286 759
ACN: 060 286 759

Ship to: SAME AS BELOW

Branch EMERALD *REPRINT*

Date 10/09/25 **Time** 00:06:40 (B) **Page** 01

[redacted]

Ship Via **Purchase Order**

ABN **ACN**

[redacted]

Salesperson TU2

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
X223495	4WD TRACTOR (WHEEL	X	RW9420P010165	14/04/05	2000
	9420	E		01/01/75	

We have relocating to new premises!
From the 12th May 2025, our new branch location is:
Cnr Capricorn Highway and Chalcedony Road Emerald 4720 QLD

SEGMENT# 1 C MWC75 NA 02/09/25 02/09/25
Inspect Transmission Fault
CONDITION:
Inspect Transmission
DIAGNOSTICS:
Inspect Transmission
REPAIR:
MWC75 3/9/25
- Travel to and inspect tractor. Found wiring rubbed on m clutch solenoid wiring so repaired wiring, reinsulated wiring and secured to stop rubbing again.
- Carried out rewire of H clutch solenoid as requested from office. Ran tractor in the field up to operating conditions and checked operation, ok. Clean up, pack up and return home.

LABOUR 495.00

10401099 SEGMENT TOTAL==> 495.00

SEGMENT# 2 C MWC75 STT-00 02/09/25 02/09/25
TECH LABOUR AND VEHICLE CHARGE
REPAIR:
MWC75 3/9/25
- Travel to tractor at property north of alpha. Carry out repairs and return to workshop after repairs. 2.5 hrs each way.

CONTINUED ON PAGE 02

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.

RDO Equipment Pty Ltd
2 Chalcedony Road
Emerald QLD 4720
Ph 07 4843 8500
ABN: 58 060 286 759
ACN: 060 286 759

Ship to: SAME AS BELOW

Branch
EMERALD

Date	Time	Page
10/09/25	00:06:40 (B)	02

[redacted]

ABN **ACN**

Salesperson
TU2

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS	
X223495	4WD TRACTOR (WHEEL	X	RW9420P010165	14/04/05	2000	
	9420	E		01/01/75		
				LABOUR		1375.00
10401099				SEGMENT TOTAL==>		1375.00

****** WORK ORDER TOTALS ******	
LABOUR	1870.00
Consumables	71.23
Environmental	56.10
SUB TOTAL==>	1997.33
GST	199.73
ON ACCOUNT	2197.06

Please remit to:
BSB: 014-657
Account: 7754 77613
Name: RDO Equipment Pty Ltd

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.

RDO Equipment Pty Ltd
2 Chalcedony Road
Emerald QLD 4720
Ph 07 4843 8500
ABN: 58 060 286 759
ACN: 060 286 759

Branch
EMERALD *REVERSE* WE8073

Ship to: SAME AS BELOW

Date 02/09/2025 **Time** 09:57:11 (B) **Page** 01

[redacted]

Field

ABN **ACN**

Salesperson
BK0

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
X223495	4WD TRACTOR (WHEEL 9420	X E	RW9420P010165	14/04/05 01/01/75	2000

We have relocating to new premises!
From the 12th May 2025, our new branch location is:
Cnr Capricorn Highway and Chalcedony Road Emerald 4720 QLD

SEGMENT# 1 C ZB075 N/A 03/07/25 07/07/25
FIT ALTERNATOR AND BELT
CONDITION:
ALTERNATOR IN TREVOR'S OFFICE
REPAIR:
fit aftermarket alternator to machine
fit new belt to alternator supplied by customer.
Replaced cam position sensor (sensor leaking customer ordered parts)
Start and test alternator charge. All ok.
NOTES:
Alternator in Trevor's office (after market)

RE519144	SPEED SENSOR	1-	75.80-	75.80-
R199163	V-BELT	1-	96.38-	96.38-
SUBLET-AG	HOSE	1-	120.40-	120.40-
			PARTS	172.18-
			LABOUR	536.25-
			SUBLET	120.40-
10301075		SEGMENT TOTAL==>		828.83-

SEGMENT# 2 C ZB075 N/A 03/07/25 08/07/25
INSPECT ELECTRICAL FAULTS
DIAGNOSTICS:
Replaced injector harness through rocker cover. (Customer has someone diagnose and said that the wiring harness is at

CONTINUED ON PAGE 02

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.

RDO Equipment Pty Ltd
2 Chalcedony Road
Emerald QLD 4720
Ph 07 4843 8500
ABN: 58 060 286 759
ACN: 060 286 759

Ship to: SAME AS BELOW

Branch
EMERALD

Date	Time	Page
02/09/2025	09:57:11 (B)	02

[redacted]

Ship Via Field
Purchase Order
ABN
ACN

Salesperson
BK0

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
X223495	4WD TRACTOR (WHEEL 9420	X E	RW9420P010165	14/04/05 01/01/75	2000

fault. No:4 injector fault old harness tested bad on No:4
and oil leaking through plug.) Tested injector harness from
rocker cover plug to ECU
found resistance on all injector wires to be 0.3 ohms or
less
tested harness through rocker cover after replacing the
harness
found fault on control wire for No:4 injector wire is
damaged internally
REPAIR:
Tested all injector wires from rocker cover plug to ECU all
tested at 0.3 ohms resistance or less no issues with
harness
Replace Transmission shift solenoid.
NOTES:
No:4 Injector wire has a high resistance.
From the injector plug to the ECU controller plug.
Wire No:399
Speed sensor leaking.

FREIGHT			1-	35.00-	35.00-
FREIGHT	FREIGHT ?		1	46.58-	46.58
FREIGHT	QuotedFreight		1-	46.58-	46.58-
RE533647	KIT		1-	974.88-	974.88-
YZ150165	SOLENOID VALVE		1-N	848.75-	848.75-
				PARTS	1858.63-
				LABOUR	1320.00-
10301075			SEGMENT TOTAL==>		3178.63-

SEGMENT# 3 C WT275 STT-00 03/07/25 11/07/25
TRAVEL TIME (LABOUR AND VEHICLE)

CONTINUED ON PAGE 03

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.

RDO Equipment Pty Ltd
2 Chalcedony Road
Emerald QLD 4720
Ph 07 4843 8500
ABN: 58 060 286 759
ACN: 060 286 759

Ship to: SAME AS BELOW

Branch EMERALD

Date	Time	Page
02/09/2025	09:57:11 (B)	03

[redacted]

Ship Via Field | **Purchase Order**

ABN | **ACN**

Salesperson BK0

[redacted]

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
X223495	4WD TRACTOR (WHEEL	X	RW9420P010165	14/04/05	2000
		E		01/01/75	

[redacted]

REPAIR:
- Travelled out to tractor and returned, 464 klm's driven.

NOTES:
Did multiple trips to farm and back.
Only charged half the trips to farm and back.

	LABOUR	2475.00-
10301075	SEGMENT TOTAL==>	2475.00-

SEGMENT# 4 C CUST NA 03/07/25 07/07/25
Low power complaint

CONDITION:
Low power complaint from customer

DIAGNOSTICS:
Inspected machine
found heavily clogged air filter
customer reported having contaminated fuel (diesel Bug)
machine did not have any active or stored codes

REPAIR:
- blew out air cleaner and recommended customer replace with a new one
- recommended changing fuel filters regardless of when they were last done due to fuel contamination issues and potential to block filters quickly
- nothing more can be done at this time told customer to monitor condition and to make sure the air cleaner is blown out regularly due to operating conditions
-Water pump stated leaking and needed to be replaced.

CONTINUED ON PAGE 04

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.

RDO Equipment Pty Ltd
2 Chalcedony Road
Emerald QLD 4720
Ph 07 4843 8500
ABN: 58 060 286 759
ACN: 060 286 759

Ship to: SAME AS BELOW

Branch
EMERALD

Date	Time	Page
02/09/2025	09:57:11 (B)	04

[redacted]

Field

ABN **ACN**

Salesperson
BK0

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
X223495	4WD TRACTOR (WHEEL	X	RW9420P010165	14/04/05	2000
	9420	E		01/01/75	

- Clean all surfaces and fit new water pump and thermostates in with new hoses, seals and clamps. Replace all vent lines and overflow lines with new hose and clamps. Fill with coolant and start tractor, top up coolant after running for a while and run tractor up to temp. Recheck level and top up again and check for leaks and for rubbing, ok. Refit guards and covers and close bonnet. Test for coolant leaks. No leaks.

NOTES:
machine working in excessively dusty conditions disc ploughing virgin ground worked machine for 100m with disc engaged and unable to see further forward than the front of the hood and could not see the second first set of discs out the rear

AH170895	CLAMP	3-	36.11-	108.33-
AR102258	THERMOSTAT	1-	67.43-	67.43-
AR21839	Clamp	2-	7.72-	15.44-
CRSE501229	CORE FOR:PUMP	1	177.00-	177.00
DZ120103	GASKET KIT	1-	407.98-	407.98-
FREIGHT		4-	68.63-	274.50-
FREIGHT	QuotedFreight	1-	236.22-	236.22-
RE224072	HOSE CLAMP	2-	27.60-	55.20-
RE33705	THERMOSTAT	1-	22.60-	22.60-
RE52702	CLAMP	3-	38.36-	115.08-
R116205	GASKET	1-N	8.73-	8.73-
R117080	Radiator Hose	1-	46.43-	46.43-
R121427	Radiator Hose	1-	37.31-	37.31-
R121443	Adapter Fitting	1-N	57.12-	57.12-
R122290	RADIATOR HOSE	1-	39.74-	39.74-
R125520	RADIATOR H	1-	171.16-	171.16-

CONTINUED ON PAGE 05

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.

RDO Equipment Pty Ltd
2 Chalcedony Road
Emerald QLD 4720
Ph 07 4843 8500
ABN: 58 060 286 759
ACN: 060 286 759

Branch
EMERALD

Ship to: SAME AS BELOW

Date 02/09/2025 **Time** 09:57:11 (B) **Page** 05

[redacted]

Field

ABN **ACN**

Salesperson
BK0

[redacted]

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS	
X223495	4WD TRACTOR (WHEEL	X	RW9420P010165	14/04/05	2000	
	9420	E		01/01/75		
R136151	Seal	1-		24.26-		24.26-
R136507	BOLT M10X70HEX	12-O		8.64-		103.68-
	Rocker/Injector (Single Use)					
R160229	HOSE	1-N		79.79-		79.79-
R56464	O-RING	1-		2.88-		2.88-
SE501229	WATER PUMP REMA	1-N		1755.64-		1755.64-
	Water Pump Reman					
CRSE501229	CORE FOR:PUMP			177.00-		177.00-
T77932	O-RING	1-S		2.89-		2.89-
19M7835	BOLT M10X35FLG	1-		1.39-		1.39-
19M7944	BOLT M10X120FLG	2-		11.68-		23.36-
19M8598	BOLT M10X170HEX	1-N		13.56-		13.56-
				PARTS		3670.72-
				LABOUR		1266.65-
10301075			SEGMENT TOTAL==>			4937.37-

SEGMENT# 5 C JH775 10-030-030 03/07/25 07/07/25
FUEL INJECTORS, REPLACE
CONDITION:
ECU Showed Injector fault codes.
DIAGNOSTICS:
Injectors have shorted out internally.
This have been caused by the injector wiring fault
previously repaired.
REPAIR:
FUEL INJECTORS, REPLACE (10-030-030)
NOTE For PARTS Fuel injector RE501010 (6) to be used on
models with SN -217335.
NOTE For PARTS, fuel injector RE518726 (6) to be used
on

CONTINUED ON PAGE 06

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.

RDO Equipment Pty Ltd
2 Chalcedony Road
Emerald QLD 4720
Ph 07 4843 8500
ABN: 58 060 286 759
ACN: 060 286 759

Ship to: SAME AS BELOW

Branch
EMERALD

Date	Time	Page
02/09/2025	09:57:11 (B)	06

[redacted]

[redacted]

Ship Via Field
Purchase Order
ABN
ACN

Salesperson
BK0

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
X223495	4WD TRACTOR (WHEEL 9420	X E	RW9420P010165	14/04/05 01/01/75	2000

models with SN217336-.
Remove high pressure fuel lines and fittings from cylinder head.
Remove rocker arm cover and spacer housing from cylinder head.
Remove fuel injection nozzles.
Clean and inspect all components.
Replace fuel injection nozzles.
Adjust injector preload.
Reinstall all components to specification.

CRSE501957	CORE FOR:INJECT	6	1045.00-	6270.00
SE501957	FUEL INJECTOR	6-N	2292.69-	13756.15-
	Elect Unit Injector Reman			
CRSE501957	CORE FOR:INJECT		1045.00-	6270.00-
			PARTS	13756.15-
			LABOUR	1716.00-
10301075		SEGMENT TOTAL==>		15472.15-

SEGMENT# 6 C WT275 NA 03/07/25 07/07/25
Replace ECU and Install software
CONDITION:
ECU replacement
DIAGNOSTICS:
Diagnose ECU injector fault codes.
Test wiring between Injector harness and ECU.
Found ECU to be faulty internally.
This could have been caused by the injector wiring fault previously repaired.

CONTINUED ON PAGE 07

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.

RDO Equipment Pty Ltd
2 Chalcedony Road
Emerald QLD 4720
Ph 07 4843 8500
ABN: 58 060 286 759
ACN: 060 286 759

Ship to: SAME AS BELOW

[redacted]

Branch EMERALD

Date **Time** **Page**

[redacted]

Ship Via Field **Purchase Order**

ABN **ACN**

Salesperson BK0

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS	
X223495	4WD TRACTOR (WHEEL	X	RW9420P010165	14/04/05	2000	
	9420	E		01/01/75		
Order new ECU						
REPAIR:						
Removed old ecu						
Installed new ecu						
Installed ecu software						
Run machine and checked for any codes						
No codes appeared						
CRSE502812	CORE FOR:CONTRO		1	627.00-		627.00
FREIGHT	SameDayFreight		1-	360.00-		360.00-
SE502812	ENG CONTROLLER		1-N	4911.11-		4911.11-
Engine Controller Reman						
CRSE502812	CORE FOR:CONTRO			627.00-		627.00-
				PARTS		5271.11-
				LABOUR		330.00-
10301075			SEGMENT TOTAL==>			5601.11-

****** WORK ORDER TOTALS ******	
PARTS	24728.79-
LABOUR	7643.90-
SUBLET	120.40-
SUB TOTAL==>	32493.09-
GST	3249.31-
CREDIT CARD	35742.40-

Please remit to:
BSB: 014-657
Account: 7754 77613
Name: RDO Equipment Pty Ltd

CONTINUED ON PAGE 08

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.

RDO Equipment Pty Ltd
2 Chalcedony Road
Emerald QLD 4720
Ph 07 4843 8500
ABN: 58 060 286 759
ACN: 060 286 759

Ship to: SAME AS BELOW

[redacted]

Branch
EMERALD

Date	Time	Page
02/09/2025	09:57:11 (B)	08

[redacted]

Ship Via Field

Purchase Order

ABN

ACN

Salesperson
BK0

WORKSHOP SERVICE TAX INVOICE

Rego / Fleet		HRS	PIN/EIN	WARRANTY DATE	HRS
X223495	4WD TRACTOR (WHEEL 9420	X E	RW9420P010165	14/04/05 01/01/75	2000

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account
Contact ar@rdoequipment.com.au for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at www.rdoequipment.com.au and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard Terms; and (2) the transaction document and the Standard Terms when read together form the contract.