




Custom Track Service
Simplified

HASTINGS DEERING
(AUSTRALIA)

Prepared By: Kurt Thompson

Model	D10T	Job Site	Emerald yarf		Inspection Date	17May22
Manufacturer	Caterpillar		<u>Left</u>	<u>Right</u>	Next Inspection Date	--
Serial Number	RJG02009	Track Sag (145 mm - 165 mm)	--	--	Next Inspection Hours	--
Reference Number	D10T3	Frame Ext (max 193 mm)	--	--	<u>Underfoot Conditions</u>	
Hour Meter Reading	--	Frame Ext %	--	--	Impact	Missing Translation: Summary
Hours Per Week	24.98	Dry Joints	--	--	Abrasion	Moderate
Total Odometer Reading	--	Link Roller System	--	--	Moisture	Low
Forward Odometer	--				Packing	Low
Reverse Odometer	--				Bushing Allowable Wear	Greater
Distance Per Week	--				Link Allowable Wear	Greater



Component	Status		Part Number		Measurement (mm)		Percent Worn	
	Left	Right	Left	Right	Left	Right	Left	Right
Sprocket								
	Replace	Replace	2782352	2782352	278	278	25%	25%

General Recommendations

--

PHOTOS

Pre-Inspect



Pre-Inspect

Measurements

Sprockets



Left Sprocket 1



Right Sprocket 1